
X−bar Control Chart − Précitech CNC Cell 3 (Simulated)
Red = specification limits (engineering tolerance)
Orange = control limits (process behaviour)
Daily mean diameter (mm)
25.06
25.04
25.02
25.00
24.98
24.96
24.94
USL
UCL
LCL
LSL
0
25
50
75
100
Production day
In control
Out of control