
Components of Variation
% of Total Variation
100
75
50
25
0
23.7%
15.7%
17.8%
97.1%
Gauge R&R
Repeatability
Reproducibility
Part−to−Part
Component


Measurement by Part
Measurement
10.08
10.04
10.00
9.96
1
2
3
4
5
6
7
8
9
10
Part
Operator
Op1
Op2
Op3


Measurement by Operator
Measurement
10.08
10.04
10.00
9.96
Op1
Op2
Op3
Operator


Part × Operator Interaction
Mean Measurement
10.08
10.04
10.00
1
2
3
4
5
6
7
8
9
10
Part
Operator
Op1
Op2
Op3