# Two−Hand Control: Both Hands Must Be on Buttons

Ensures operator's hands are away from the danger zone during machine cycle

Both buttons pressed within 0.5 seconds

Anti−tie−down prevents bypassing