

AIAG Automotive Core Tools

Five essential tools required by IATF 16949

APQP
Advanced Product
Quality Planning
Define quality requirements and define controls

PPAP
Production Part
Approval Process
Control production quality

FMEA
Failure Mode & Effects Analysis
Identify and mitigate risks

MSA
Measurement
Systems Analysis
Ensure measurement reliability

SPC
Statistical
Process Control
Identify control process