

The Six Big Losses: Targets for TPM Improvement

AVAILABILITY LOSSES

1

Equipment
Failure

2

Setup &
Adjustment

PERFORMANCE LOSSES

3

Idling &
Minor Stops

4

Reduced
Speed

QUALITY LOSSES

5

Process
Defects

6

Startup
Rejects