


. In order to map the process activities you'll need approximately one month.									
· list of #TOTAL STEPS	# VALUE CREATING STEPS (·)		#TOTALTIME	#VALUE CREATING					
· Summary: Tsteps 73		(·) Value Creating: Customer is	Whatever the eady to pay for.					
Time 44/3 d	Value Creating	5	Westschöpfend)	1/244					
Distance: 53 #tromsport hu	1 1 1	44'3 d	44 ¹ 3d 10 ³						
of time while they a getting one unit of t	wehai	The managerial interpretation is that for every value creating unimute we have 1000 non-value creating unimutes.							
getting one unit of t value creation!		Bench	mark Coo	TOYOTA 1					

The information is useful but not not actionable.
We need to map the process (wrient state) so that managers can act on it.



CURRENT STATE MAP

Dearborn H., Mi SteelCoils

Cleveland OH 960 Pieces do y 640 A 320 B

		Beta Whipers Warehouse		Reta Whiters Cross-Dock	phanotus rok-Dak		
(3)	Garman a Stamping	4	Beta Whipers Assy.	6		A pha Notors Assy.	
	Towananda, NY	Harlingen,TX	Reynosa, Mexico	Harlingen, TX E	t Paso, TX	West Drange, N	J
	RM. 336h wip. 110 h		RM 56h Wif 41h			RM Soh Wip 2h	
	FG.48h		FG 12h			FG 14h	
	3 shifts 5 Days		2 Shifts 5 Days			2 Shifts 5 Days	
<u>~</u>	EPE1: 3 Days		EAEI 1024			EPE 1 Dav	1
((2)	Q:2000ppm	(f)	Q 400pm		(12)	5 ppm	

RM: Raw Material Inventory [h] (coverage Time) Wip: Work in Progress Inventory FG: Finished Goods Inventory