
Supplier Audits

In Idealfall, geht man vor der 15T-SOLL Prosefausgleich zu ermitteln.

DESIRED - CURRENT - D
STATE - STATE

We (supplier Manager) perform an Audit to weasure the current state and compare it with a standard (desired state).

We aim to measure the current state of the process, however a process is a complex reality that can only be explained with multiple KPis.



LFFICIENCY (HPU) (=/UNIT)



There is no way to explain the whole variability of the process with one kpi.
The only way to know that we're good is

by bolling at several UPIs. This allows us to explain
by booking at several KPIs. This allows us to explain a higher amount of variability related to the process
An Avoit is a qualitative approach to inspect the variability related to processes.
Example. Order & Cleanliness
1. Avdit leader = Supplier Manager
1. Avditleade, = Supplier Manager Company _ Date Department_Begin
Workplace _ End
convierts_
3. Instructions.
3.1. Who does the audit?
-> Must be performed by at least 2 auditors. One should be from the outside of the process A process owner should accompany the audit
One should be from The outside of the process
T process owner smould recombant the and it

-> PROCESS KNOWLEDGE. Process Duner AUDIT 11. Audit leader

3.2. When to we perform the audit!
-> while the precess is running.
-> while the precess is running> whithout previous notice.
3.3. Important aspects for team members
- An audit; sa method to empower. It should generate trust.
It should generate trust.
-> We audit processes, not people.
-> We audit processes, hat people. -> You inform about the ANDIT Questions
Up honty.
-> Every audit member should be present
all the time.
all the time. The expect objective evaluation. Ask alwayswhy?
always Why!
4. Ruestions55"
as stipi - Li - Li - Hornala - Mithage in
Sort Sorting Thought all ITEMS IN
a botton and remove all
Unviecessary wan ine
15) SEIRI. "sort". Sorting through all items in a location and remove all universary from the workplace. 25) SEITON Set in order put all necessary
ETION Set in order put all necessary
items in the optimal place for full filling their function
or hilling their functions

