

H-60 Improvement Plan

Plain-English version — updated August 20, 2026 — Companion to **docs/IMPROVEMENT_PLAN.md** (the technical version, same folder)

The short version: the H-60 mod works, but under the hood it has grown messy — duplicate files, conflicting copies of the same settings, a few genuine bugs, an outdated build process, and no automatic checks to stop new mistakes. The two reference mods (the AH-64D Apache and the MH-47G Chinook) solved all of these problems in almost exactly the same way as each other. This plan copies their homework, in seven steps, ordered so each step makes the next one safer.

What was studied

A full read-through of three codebases: the AH-64D Apache project (the gold standard for project setup — build tools, automated checks, documentation), the PGS MH-47G Chinook (the gold standard for simulating aircraft systems — engines, electrics, warnings), and the H-60 itself (a top-to-bottom audit looking for bugs, clutter, and inconsistency). A bonus discovery: the Chinook is built on the same Hatchet cockpit-interaction framework the H-60 uses, and its comments even credit the H-60 for several tricks. So these patterns are proven to work with this exact setup.

The big idea the reference mods share

Both reference mods, built by different teams, landed on the same rules:

- **One master blueprint.** The helicopter's base definition (its "template") lives in exactly one place. Every other package only adds to it — it never rewrites it. The H-60 currently has four different files all claiming to define the master template, and the game just picks whichever loads last. That's the root cause of things mysteriously breaking when unrelated parts change.
- **Numbers live in settings files, not buried in code.** Engine power tables, weights, warning thresholds — kept as data the game can reload live, so tuning doesn't require rebuilding the mod each time.
- **Each helicopter keeps its own scorecard.** Information about a specific aircraft (is engine 1 running? how much does it weigh?) is stored on that aircraft. The H-60 sometimes stores it in shared global variables — which means two Blackhawks in the same mission overwrite each other's data.
- **A robot checks every change.** Both reference projects (especially the Apache) have automated checks that reject badly named files, broken references, and missing translations before a human ever sees them. The H-60's version of this was switched off — the checking step in the automation is literally commented out, and the checker scripts it refers to don't exist.

What's actually wrong with the H-60 today

1. Real bugs, live right now. The rescue hoist's "raise" function accidentally calls the "lower" function when someone else's machine owns the aircraft (a copy-paste slip). It also targets the wrong helicopter on dedicated servers. A lookup table for the helicopter's paint/parts slots is off by one — five entries point at the wrong slot. The engine startup code initializes engine 1's power twice and engine 2's never, quietly re-registers the same event listener every time you board (they pile up), and uses shared variables so multiple

Blackhawks corrupt each other. Debug leftovers ship to players: one function prints "SETTING UP" chat spam to everyone nearby, another writes to the log every frame.

2. Clutter. About 45 files are dead weight: empty files, abandoned half-finished rewrites, and three different copies of the same important settings file that have drifted apart (108 lines now differ between copies — nobody knows which is "the real one"). There's also an entire hidden Pong game living inside the cockpit-display package.

3. No consistency. The mod has three different styles of registering script functions, four different styles of registering mod options, and almost no translations (248 pieces of English text are hardcoded; only 5 use the translation system). One in-repo package (ace_viv) does everything the right way — the plan is basically "make everything look like that one."

4. An outdated, partly broken build process. The tool that packages the mod is Windows-only, uses a trick that silently skips a whole optimization step (it points the optimizer at a fake program), and the version number is written in four different places that all disagree. Both reference mods use a modern tool called HEMTT that fixes all of this and stamps the version automatically.

The plan, step by step

STEP 0 · SMALL & IMMEDIATE

Fix the real bugs

Fix the twelve concrete bugs found (hoist, engine startup, off-by-one table, chat spam, plus two confirmed from the public bug tracker: the laser-code error that spams server logs, and the flight-director keybinds that do nothing because they ask for a cockpit knob by the wrong name). No redesign — just corrections. Test with two Blackhawks at once on a dedicated server, since that's where most of these bite.

STEP 1 · THE FOUNDATION

One master blueprint

Merge the four competing definitions of the helicopter template into one place (the main UH60 package), with the others only adding their piece on top. This is the earlier "Snow game plan," but corrected — review found it missed a fifth duplicate (the HH-60 variant), described sound-package content that doesn't exist, and would have silently deleted the minigun cockpit controls and paint schemes if followed word-for-word. The technical version of this document has the full correction list. Before-and-after snapshots of every helicopter's resolved settings prove nothing changed by accident.

STEP 2 · SPRING CLEANING

Delete the clutter

Remove the ~45 dead files, merge the triplicate settings files into one, and fix 12 file references that only work because Windows ignores capitalization ("CfgVehicles" vs "cfgVehicles"). That capitalization fix is required before Step 3 — the new build tool runs on Linux, which does care.

STEP 3 · MODERN TOOLS

New build system + automatic checks

Switch to HEMTT, copying the Apache project's setup: the version number lives in one file and gets stamped everywhere automatically; a one-command launcher starts the game with the right mods for

testing; and every change pushed to GitHub gets automatically checked for naming mistakes, broken references, and missing files. Someone on the team already started this migration once (there's an abandoned branch) — this finishes the job.

STEP 4 · ONE WAY OF DOING THINGS

Consistency pass

Pick one style for everything — function registration, mod options, translations, naming — and convert packages to it gradually as they're touched (not in one giant risky rewrite). Also fix the dependency declarations so the game loads packages in a guaranteed order: right now many packages call each other without declaring it, and — backwards — the base helicopter package depends on five of its own add-ons. The fix flips that around: each add-on contributes its own cockpit switches instead of the base knowing about everyone.

STEP 5 · THE PAYOFF

Better systems, borrowed from the Chinook

- **Engine & electrics:** the H-60 currently ships two generations of engine code side by side. Finish the new one, delete the old, and structure it the Chinook way — one orderly pass every second (battery → APU → hydraulics → fuel → engines), where flipping any switch mid-start correctly aborts the start. No more wedged states.
- **Warnings:** rebuild the caution/warning system as a simple checklist table (severity, message, condition) that the master-caution light and displays read from — every warning tied to real damage or real system state. Newly added here: a proper advisory, worded like the real aircraft's caution list, for when a player has the game's picture-in-picture setting disabled — today that silently blanks the FLIR screens and has already produced a false bug report.
- **Cockpit displays:** one master list of which display slot means what (right now three conflicting copies exist and some code uses raw numbers), plus the Apache's tool that auto-generates documentation from that list and fails the build if two things claim the same slot.
- **Hoist:** rewrite its motion loop properly (it currently spins a loop as fast as the computer allows).
- **Performance numbers** (hover power, cruise power, weights) move into reloadable data tables so tuning takes seconds, not rebuilds.

STEP 6 · KEEPING IT GOOD

Documentation & habits

A README that actually explains how the mod is organized; a short contributor guide with the project's rules written down and named (the Chinook team names their rules — "the shadow-not-merge law" — and cites them in reviews, which works); a pull-request checklist; one changelog instead of two; and the Chinook's best habit: every non-obvious decision gets a dated comment explaining why, and failed experiments are kept as labeled warnings so nobody retries them.

Checking the public bug tracker

All 17 open reports on the GitHub project page were reviewed. Good news: every single one fits inside this plan — nothing contradicts it, and several reports independently confirm what the plan already says. Highlights:

- **"No sound dampening in the cockpit"** (confirmed by the team, unfixed) — this is almost certainly the four-competing-blueprints problem from Step 1. The sound package's settings silently lose the load-order lottery. Fixing Step 1 should fix this, and it becomes the test that proves Step 1 worked.
- **"Server crashed from network overload with 10 Blackhawks"** — matches two things the audit found: the engine code quietly stacks up duplicate listeners every time someone boards, and several scripts broadcast far more than they need to. Steps 0 and 5 target exactly this.
- **"FLIR tracking worked 50% of the time, now not at all"** — traced and fixed (an update accidentally made the lock key do nothing in the camera view people actually use, and the lock-on search was too fragile to catch big, moving, or flying targets).
- **"Copilot cockpit vanished without anyone changing anything"** — traced and fixed (August 2026). A previous update turned the copilot seat into an "optics turret," which makes the game engine ask the 3-D model for an interior view it doesn't have, so the game fell back to a stripped-down stand-in — hence the see-through console. The copilot seat now uses the proven standard setup on every variant; the dedicated camera-operator seat returns once the model itself gains that missing interior view.
- **Two reports turned out to be exact, confirmable bugs** — a laser-code script error and dead flight-director keybinds (they ask for a cockpit knob that's spelled differently in the cockpit files). Both added to Step 0. The keybind one also has a second half that lives in the shared Hatchet framework, not this mod — fixed there directly.
- **The feature requests are cheaper than they look:** the requested IZLID laser exists fully working in the Chinook (copyable), the "add/remove fuel tanks via ACE" request is exactly how the Apache does its equipment swapping (copyable), and the better-waypoints request matches the Apache's navigation package (a design to follow). Each becomes a straightforward port once the groundwork phases are done.

What could go wrong, and the safety nets

- **Step 1 is the riskiest** — it moves the most config. Safety net: an automated before/after comparison of every helicopter variant's full resolved settings, plus spawning every variant in the editor.
- **Step 5's engine cutover** — keep the old code deletable in a single commit, so if something's wrong we can pinpoint it fast.
- **Multiplayer bugs** — build a small standing test mission (dedicated server + two players, one of whom doesn't own the helicopter). That's exactly how the Chinook team caught their hardest bugs, and it's how the hoist bug here would have been caught.

Five decisions for the maintainer

Question	Status / recommendation
Rename the released mod files? (One-time hassle for server owners.)	Decided (Aug 18): the hct branding stays in filenames — target <code>hct_h60_<component></code> with the redundant middle dropped, done during the Step 3 build-tool migration and announced in the changelog so server owners change their lists once. The older internal vtx prefix stays in code for now; renaming it is a known long-term wish but a breaking change that gets its own plan, never a side effect.
Convert all 2,188 old-style names at once, or	Gradually, as files get touched. A one-shot rewrite is high-risk for zero player benefit.

gradually?	
Fully merge the uh60_config package into the base, or keep it as a small add-on layer?	Keep it as an add-on layer — that's the pattern both reference mods use.
The hidden Pong game in the MFD package: keep or delete?	Maintainer's call entirely. Keeping it as an easter egg is fine; it just needs its duplicate files cleaned up (already in Step 2).
How far to take translations?	First make English complete in the translation system; invite actual translations later.

Technical companion: **docs/IMPROVEMENT_PLAN.md** in this folder has every file path, line number, and code pattern behind each item here. This is a plan document — the fixes land through the repository's normal pull requests.