

Service Report 7098_230719085922

То:		For:							
Contact Name	Sophie Merlin	Date	19-Jul-2023 10:59 AM						
Contact Email	s.merlin@genesdiffusion.com	Work Order Number	WO-00827098						
Contact Phone	+33320877890	Case Number	03336789						
Account									
Name	Genes Diffusion	Address	3595 route de Tournai CS 70023, Douai CEDEX, Nord, 59501, France						
Work Order Details									
Installed Product	N0257-11279781	Work Order Record Type	Field Service						
Product	ASSY.SCANNER, iScan	Work Order Order Type	Service Activities						

Problem Description

External message, be mindful when clicking links or attachments Bonjour Illumina team tech, l'un des fours de notre plateforme de gér chauffage est correcte, toutefois, il est anormalement bruyant. Préférant anticiper tout risque de panne qui bloquerait notre activité, qu' type de problème? Je place ma collègue L.Liétar (responsable de la plateforme 0327992949) en copie de ce mail, qui sera à même d Bien cdt, [GD

Biotech]https://www.gdbiotech.eu__;!!HrbR-XT-OQ!RMmJ5jkAljxSJGKeiTdYqnAQOJfniro14_uGRSC4j0s1 MERLIN Biomolecular Engineer, Purchasing Manager Tél. : 03 20 87 78 90 Port. :

www.gdbiotech.eu<https://urldefense.com/v3/__http://www.gdbiotech.eu__;!!HrbR-XT-OQ!RMmJ5jkAljxSJGKeiTdYqnAQOJfniro14_uC [LinkedIN GD Biotech]

https://urldefense.com/v3/_http://www.linkedin.com/company/86142849_">https://urldefense.com/v3/_http://www.linkedin.com/company/86142849_"
linstitut Pasteur de Lille, 1 rue du professeur Calmette 59000 LILLE [https://adfs.aei-arsoe.com/adfs/portal/images/globe.png] Adopt the

		-,			3 3	. 1. 01			
Closure									
Evaluatio	on	24 MAY 2023 : Customer is complaining about anormal noise on their Hybridization oven							
Work Pe	rformed	06 JUN 2023 FSE on site: Oven Replaced and installed according to the Iscan Installation Guide 13 JUL 2023 FSE on site: Adjustement done for the 48°C. (read 48.3 for set 48)							
Verification	on	06 JUN 2023 FSE on site : All tests passed, temperatures are within specification 13 JUL 2023 FSE on site : Double checked with the customer probe							
Billing De	etails								
Service Contract End Date									
iScan Bro	Scan Bronze Support Plan 24-Oct-2023								
PO Number N/A									
Parts Use	ed								
Part Number	Description	n		Lot /Serial Number	Quantity	Туре	Reason Not Billed		
11277501	hybridizatio	a Hybridization Oven is custom-fitted with a rotating hybridization when on steps. The wheel has a variable rotation speed of 5-60 rpm and the e ramp from ambient to 65'C in 25 minutes. The oven holds up to 24 B	oven has a	N/A	1	Spare			

time. (22	20V)										
Material Consumed											
Part Number	Description	Lot /Serial Number C		Quant	ity	Type	Reason Not Billed				
Tools Used											
Part Number	Description			Seri	Serial Number		Calibration Due date				
20033632	DUAL INPUT DIGITAL THERMOMETER			3743	37430681WS 12			12-Aug-2023			
Labor & Travel Details											
Field Support	Activity Type	Labor Hours	Travel Hours	R	Reason Not Billed		S	Start Date and Time			•
Hassan hadiri	Repair/Troubleshooting	4	2				1	I3-Jul	-2023 12	:00 PM	1
Hassan hadiri	Repair/Troubleshooting	4	2				0)6-Jur	n-2023 10	1A 00:0	M

Illumina France SARL

52 Boulevard de Sebastopol

PARIS

France

75003

Illumina Signature

Customer Signature

Signature: Hassan hadir Jul 19, 2023 11:03 GMT+2)

Email: hhadiri@illumina.com

Signature: S.Merlin (Jul 19, 2023 11:08 GMT+2)

Email: s.merlin@genesdiffusion.com