

Service Report 1395_201025112922

То:				For:				
Contact Name		Sophie Merlin		Date		25-Oct-2020 12:29 PM		
Contact Email		s.merlin@genesdiffusion.com		Work Order Number		WO-00501395		
Contact Phone		+33320877890		Case Number		02076428		
Account		1		1				
Name		Genes Diffusion		Address		3595 route de Tournai BP 70023, Douai, Nord, 59500, France		
Work Order Details								
Installed Product		N0257-11279781		Work Order Record Type		Field Service		
Product		ASSY.SCANNER, iScan		Work Order Order Type		Service Activities		
Problem Description								
Customer reported red laser to have failed and is below specification. ICS error: Error message: The scan cannot proceed because the red laser power output is below specification.								
Closure								
Evaluation	Service contract: Bronze # 8000054714 Account # 6000000875							
Work Performed	23-Oct-2020: FSE Onsite. Red Laser need to be replaced. FSE replaced the Red Laser as par service Guide. Adjustements done							
Verification Results	Verification completed. Run Customers Samples after the service visite							
Billing Details								
Service Contract				Service Contract End Date				
iScan Bronze Support Plan				24-Oct-2021				
PO Number				N/A				
Parts Used								
Part Number	Descr	<u> </u>	Lot /Serial N	umber	Quantity		Туре	
15005106S	S SPARE, COHERENT RED LASER, 658NM		N/A 1				Spare	
Tools Used								
Part Number	Description			Serial Number		Calibra	Calibration Due date	
5063941 TOOL, Sensor Wand 818-ST2-UV/DB		, Newprt,	0477		02-Jul-	2-Jul-2021 9:00 AM		
Labor & Travel Deta	ails							
Field Support Activit		y Type Labor Hours		Start Date and Time		е	End Date and Time	
acky Bismuth Repai		Troubleshooting 9:30		23-Oct-2020 9:00 AM		1	23-Oct-2020 6:30 PM	

Illumina Signature

Jacky Bismuth

Customer Signature