Developing a textile bend sensor

List of Material

Number	Material
1	Copper Tape
2	Battery holder(6V)
3	EeonTex Conductive Fabric or Velostat
4	Conductive thread
5	Stretchable Conductive Fabric
6	Neoprene or some substitute
	(expected thickness: 1.5 mm)
7	Battery 5 V
8	Multimeter
9	LED

For dimention, please refer Low-fi prototype and cut in according to your sensor size.