Project : Developing a Textile Bend Sensor

GANTT CHART								
		Week 1	Week 2	Week 3	Week 4	Week 5	Week 6	Week 7 & 8
Task Number	Task Name	June 18- June 24	June 24- July 1	July 2- July 8	July 9- July 15	July 16- July 22	July 23- July 29	July 30 - August 12
1	Gathering remaining required materials							
2	Find substitute of non-acquired materials							
3	Improvisation in design if necessary (based on material).							
4	Developing a Sensor							
5	Fine-tuning of the developed Sensor							
6	Pilot Run for Evaluation							
7	Finalization and Testing							