

0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

0 in 1 2 3 4 5 6 7





**2. 3. 4. 5. 8. S** howto.prusa3d.cz

	2x M10x350
	2x M8x370
	2x 8x330 2x 8x320
	1x 10x470
	1x 8x240
	1x 6x200

32  
CICKER


v1.0

0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18


0 in 1 2 3 4 5 6 7

## 2. Y-AXIS

[howto.prusa3d.cz](http://howto.prusa3d.cz)



14x M10n




22(+2)x M8n



1x M3nN




12x M10w




22x M8w



2x M3w



2x M3x10



2x M3x12



2x M2x12




1x M3x25



3x LM8UU



1x GT2-16



1x Y-GT2



1x 623h

14(+2)x 2.5x100

PRUSA  
RESEARCH  
V1.0


PICKER  
13



## 2. Y-AXIS

[howto.prusa3d.cz](http://howto.prusa3d.cz)

- 4x Y-Corner
- 1x Y-Motor
- 1x Y-Belt-Holder
- 1x Y-Idle
- 1x PSU-Y-Part



### 3. X-AXIS


[howto.prusa3d.cz](http://howto.prusa3d.cz)


1x X-end-motor

1x X-end-idler

1x X-carriage

**PRUSA**  
**RESEARCH**







## 4. Z-AXIS


[howto.prusa3d.cz](http://howto.prusa3d.cz)




4x M3n



8x M3w



18x M3x10



4x M3x12



1x X-GT2



7(+1)x 2.5x100



**PRUSA**  
**RESEARCH**

0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

0 in 1 2 3 4 5 6 7

1 cm 1 2 3 4 5 6 7 8 9  
1 in 1 2 3 4 5 6 7 8 9  
2 cm 1 2 3 4 5 6 7 8 9  
2 in 1 2 3 4 5 6 7 8 9  
3 cm 1 2 3 4 5 6 7 8 9  
3 in 1 2 3 4 5 6 7 8 9  
4 cm 1 2 3 4 5 6 7 8 9  
4 in 1 2 3 4 5 6 7 8 9  
5 cm 1 2 3 4 5 6 7 8 9  
5 in 1 2 3 4 5 6 7 8 9  
6 cm 1 2 3 4 5 6 7 8 9  
6 in 1 2 3 4 5 6 7 8 9  
7 cm 1 2 3 4 5 6 7 8 9  
7 in 1 2 3 4 5 6 7 8 9  
8 cm 1 2 3 4 5 6 7 8 9  
8 in 1 2 3 4 5 6 7 8 9  
9 cm 1 2 3 4 5 6 7 8 9  
9 in 1 2 3 4 5 6 7 8 9  
10 cm 1 2 3 4 5 6 7 8 9  
10 in 1 2 3 4 5 6 7 8 9  
11 cm 1 2 3 4 5 6 7 8 9  
11 in 1 2 3 4 5 6 7 8 9  
12 cm 1 2 3 4 5 6 7 8 9  
12 in 1 2 3 4 5 6 7 8 9  
13 cm 1 2 3 4 5 6 7 8 9  
13 in 1 2 3 4 5 6 7 8 9  
14 cm 1 2 3 4 5 6 7 8 9  
14 in 1 2 3 4 5 6 7 8 9  
15 cm 1 2 3 4 5 6 7 8 9  
15 in 1 2 3 4 5 6 7 8 9  
16 cm 1 2 3 4 5 6 7 8 9  
16 in 1 2 3 4 5 6 7 8 9  
17 cm 1 2 3 4 5 6 7 8 9  
17 in 1 2 3 4 5 6 7 8 9  
18 cm 1 2 3 4 5 6 7 8 9  
18 in 1 2 3 4 5 6 7 8 9  
19 cm 1 2 3 4 5 6 7 8 9  
19 in 1 2 3 4 5 6 7 8 9  
20 cm 1 2 3 4 5 6 7 8 9  
20 in 1 2 3 4 5 6 7 8 9  
21 cm 1 2 3 4 5 6 7 8 9  
21 in 1 2 3 4 5 6 7 8 9  
22 cm 1 2 3 4 5 6 7 8 9  
22 in 1 2 3 4 5 6 7 8 9  
23 cm 1 2 3 4 5 6 7 8 9  
23 in 1 2 3 4 5 6 7 8 9  
24 cm 1 2 3 4 5 6 7 8 9  
24 in 1 2 3 4 5 6 7 8 9  
25 cm 1 2 3 4 5 6 7 8 9  
25 in 1 2 3 4 5 6 7 8 9


## 4. Z-AXIS

[howto.prusa3d.cz](http://howto.prusa3d.cz)


- 2x Z-screw-cover
- 1x Z-axis-top-left
- 1x Z-axis-top-right
- 1x Z-axis-bottom-left
- 1x Z-axis-bottom-right



**PRUSA**  
**RESEARCH**



0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25  
0 in 1 2 3 4 5 6 7




0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18  
0 in 1 2 3 4 5 6 7

1 cm 1 2 3 4 5 6  
1 in 1 2 3 4 5 6

6. LCD

[howto.prusa3d.cz](http://howto.prusa3d.cz)



0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19  
0 in 1 2 3 4 5 6 7

## 6. LCD


[howto.prusa3d.cz](http://howto.prusa3d.cz)

- 1x LCD-cover
- 1x LCD-knob
- 1x LCD-supportA
- 1x LCD-supportB
- 4x LCD-cable-clip

PICKER  
6

PRUSA  
RESEARCH

0 cm 1 2 3 4 5 6 7 8 9  
0 in 1 2 3 4 5 6 7 8 9  
10 11 12 13 14 15 16 17 18 19  
10 11 12 13 14 15 16 17 18 19  
20 21 22 23 24 25



## 7. PSU & HB

[howto.prusa3d.cz](http://howto.prusa3d.cz)

- 1x Heatbed-cable-cover
- 2x Spool holder

PICKER  
30

**PRUSA**  
**RESEARCH**

0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

0 in 1 2 3 4 5 6 7

1 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

1 in 1 2 3 4 5 6 7



## 7. PSU & HB

[howto.prusa3d.cz](http://howto.prusa3d.cz)




3x M3n



2x M3w



2x M3x18



2x M4x10r




5x M3x8r



2(+1)x 2.5x100



**PRUSA**  
**RESEARCH**





0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25  
0 in 1 2 3 4 5 6 7


8. ELE

[howto.prusa3d.cz](http://howto.prusa3d.cz)



0 cm 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18  
0 in 1 2 3 4 5 6 7

## 2. 3. 4. 5. SUP [howto.prusa3d.cz](http://howto.prusa3d.cz)



1x 5015 fan

4x FeltPad

1x P.I.N.D.A. probe

2x Endstop


**PRUSA**  
RESEARCH

1x Nozzle

1x Fan



**PRUSA**  
**RESEARCH**



## 0. TOOLS

[howto.prusa3d.cz](http://howto.prusa3d.cz)