<b>▲</b>	\$ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11		3085 3085 1 un in itelor i	TCARM3 00 TCARM3 Pagina
	**************************************	- U		PRIZA PRIZA PRIZA  PRIZA PRIZA PRIZA  PRIZA = 2.8 2.8 2.8  14.3 14.3 14.3  20A/P+N 20A/P+N 20A/P+N 0.03	SCHEMA MONOFILARA TCARM3
	× × × × × × × × × × × × × × × × × × ×	d/		228 2.8 14.3 20A/P+N 0.03 - NZXH 364 364 364  Project: In In Project: In	Investitor Denumire c
	25 £			PRIZA PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 0.03 0.03 0.03 0.03 0.04 0.05 0.05 0.07 0.09 0.09 0.09 0.09 0.09 0.09 0.09	SEMNATURA
	020 020	e e e e e e e e e e e e e e e e e e e		PRIZA PRIZA  2.8  14.3  20A/P+N  0.03  0.03  NZXH  3G4  Invexatute cu o rezerva de sistemului trebului es de valic atalica a tabloului electric se va verifica vizual si se stric se va verifica vizual se stric se va verifica vizual se stric se v	NUME Arh.Christian TANASCAUX Ing. Liviu POPA- BELEGANTE Ing. lonel OPREA Ing. Constantin SAMOILA
	650 X	11		PRIZA  2.8  14.3  20A/P+N  0.03  -  NZXH  0.03  -  NZXH  3G4    P-31  Carcasa melta lintrari -lesiri o Tabloul va fi p Conceptia sis Carcasa melta Tabloul va fi p Conceptia sis Carcasa melta Tabloul lefort Pappara Carcasa melta Tabloul lefort Pappara Carcasa melta Tabloul lefort Pappara Carcasa melta Tabloul lefort SexPERI    VERIFICATOR / EXPERI   EXP	SPECIFICATIE SEF PROIECT MANAGER PROIECT VERIFICAT DESENAT
	85	N.		PRIZA Priza c-arm e3076 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	£ 1	N.	*   K	PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	95 T	- W		C16 PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	\$5.00 **			PRIZA PRIZA 14.3 20A/P+N 0.03 - NZXH 3G4	
	410 *	N		C14 PRIZA Priza c-arm e3013 2.8 14.3 20A/P+N 0.03 - N2XH 364	
	\$60 ************************************			C13 PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	21.0 21.0			C12 PRIZA Priza c-arm e3019 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	÷ 1	et e e		PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<i>1</i> /		C10 PRIZA PRIZA 2.8 14.3 20AP+N 0.03 - NZXH 3G4	
	8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			PRIZA PRIZA  2.8  14.3 20AP+N  0.03  - NZXH  3G4	
	8 1	J/		C8 PRIZA Priza c-arm e3041 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	6	<i>y</i>		PRIZA PRIZA 2.8 14.3 20AP+N 0.03 - NZXH 3G4	
	8	J/		Deriza c-arm e3109  2.8  14.3  20A/P+N  0.03   NZXH  364  Wonitorizare UC10*  A618	
	8 1	N		PRIZA PRIZA PRIZA 14.3 20AP+N 0.03 0.03  NZXH 3G4  Nonitorizare Interupator A619	
	* 1	<i>1</i> /		PRIZA Priza c-arm e3101 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	**************************************			C3 PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	8 1			PRIZA PRIZA PRIZA 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	ō 1	<i>y</i>		C1 PRIZA Priza c-arm e3069 2.8 14.3 20A/P+N 0.03 - NZXH 3G4	
	8	<b>J</b> III		DESCARCATOR SUPRATENSIUNI ATMOSFERICE	
230V/400V - 50Hz	S S	<b>,</b> III	\rightarrow \righ	A A SIGNAL OF THE STATE OF THE	N2XH 3G4
530	8	<i>;;;;</i>		1.TOR CARM3	3G4
de la TGD2					Tip Cablu Sectiune