Grasp run: a steady 0.13–0.17 rad shoulder offset, and a false alarm at the end

Same sag as in the bench test. Excluding side down, the largest shoulder-pitch error is 0.17 rad (it reaches 0.98 rad inside side down).