




1)Temperature alert (max 88)




2)Downtime reasons and downtime overtime



3)Defect rate and downtime hours




4) Machine status



5) Production trends and total units



6) Defects



7) Recent maintenance log



8) Sensor trends

