

MANGALORE REFINERY AND PETROCHEMICALS LIMITED (MRPL)

EQUIPMENT INSPECTION REPORT

Document ID: MRPL-IR-2026-PUMP03

Unit: CDU-II Cracking & Pumping Section

Date: 2026-09-03

Equipment: Pump-03 Main Cooling Water Circulation Pump

Parameter: Bearing Temperature

Observed Value: 92 degrees C

Operational Limit: 80 degrees C max continuous

Condition: Abnormal heating observed during routine daily round.

Evidence: Temperature sensor PT-204 recorded 92 degrees C under normal load.

Observation: Heavy casing vibration and localized overheating detected on bearing housing.

MANGALORE REFINERY AND PETROCHEMICALS LIMITED (MRPL)

EQUIPMENT INSPECTION REPORT - PAGE 2

Equipment: Pump-03 Main Cooling Water Circulation Pump

Visual Inspection Details:

- Lubrication level adequate but oil discoloration observed at sight glass.
- Bearing temperature recorded for Pump-03 reached 92 degrees C.
- Acoustic inspection indicates early race wear in inboard bearing assembly.
- Recommended action: Immediate advisory review and planned bearing replacement.