

Noqsi Aerospace, Ltd. 2822 South Nova Road, Pine, Colorado, USA 80470


+1-303-816-2756 jpd@noqsi.com





.subckt Booster %up




TITLE	Parallel clock current booster					
FILE:	Booster.sch					
DATE	Tue May 19 08:43:54 2015 -0600	REVISION: FPE-6.1-RR8				
PAGE	1 OF 1	DRAWN BY:	jpd			












Parallel Clock Drivers


Noqsi Aerospace, Ltd. 2822 South Nova Road, Pine, Colorado, USA 80470

+1-303-816-2756 jpd@noqsi.com










Noqsi Aerospace, Ltd. 2822 South Nova Road, Pine, Colorado, USA 80470

+1-303-816-2756 jpd@noqsi.com



TITLE	Driver Set						
FILE:	DriverSe	et.5.sch					
DATE	Tue May	19 08:43:54	2015 -0600	REVISION: FPE-6	5.1–RR8		
PAGE	5	OF	5	DRAWN BY:	jpd		

May 20, 15 10:11	Table of Content	Page 1/	1					
Table of Contents								
1 Booster.ps sheets	1 to 1 (1) pages	1- 1 1 lines						
2 ParallelPair.ps sheets	1 to 2 (2) pages	1- 2 1 lines						
3 ParallelReg.ps sheets	2 to 3 (2) pages	2- 3 1 lines						
4 SerialDriver.ps sheets	3 to 4 (2) pages	3- 4 1 lines						
5 SerialRegulator.ps sheets	4 to 5 (2) pages	4- 5 1 lines						
6 DriverSet.1.ps sheets	5 to 6 (2) pages	5- 6 1 lines						
7 DriverSet.2.ps sheets	6 to 7 (2) pages	6- 7 1 lines						
8 DriverSet.3.ps sheets	7 to 8 (2) pages	7- 8 1 lines						
9 DriverSet.4.ps sheets	8 to 9 (2) pages	8- 9 1 lines						
10 DriverSet.5.ps sheets	9 to 10 (2) pages	9- 10 1 lines						