## QATCH Technologies Release Notes

	Software v2.6r63	Firmware v2.6r63
	Updated build info Release date 10/09/2025	Updated build info Release date 10/09/2025
Features & Enhancements Added	<ul> <li>Updated build information and resources to v36</li> <li>Upgraded to QModel v4 (Fusion) with PyTorch backend</li> <li>Merge issue #203: Switch from TensorFlow to PyTorch.</li> <li>Merge issue #84: NEW: VisQ.Al.</li> <li>Merge issue #206: Interpolated viscosity reporting.</li> <li>Merge issue #193: License server integration and bugfixes</li> <li>Merge issue #184: Improve analyze footnote formatting.</li> <li>Merge issue #177: Add temperature handling to table.</li> <li>Merge issue #175: Rename "Predict" to "Auto-Fit"</li> <li>Merge issue #171: Remove live fill forecasting.</li> <li>Merge issue #168: Add missing icon for run info window.</li> <li>Merge issue #160: Delete image clustering module</li> <li>Merge issue #158: Protections against pruning base model</li> <li>Merge issue #147: Hide POI3 from UI.</li> <li>Add device fingerprinting for license management</li> <li>Implement constraint-based sampler and optimizer</li> <li>Add batch processing mode for loading multiple runs</li> <li>Enhance protein handling with new ProteinClass enum</li> <li>Add progress dialog for model prediction feedback</li> <li>Improve error handling and logging across modules</li> <li>Add viscosity average and standard deviation to analysis.</li> <li>Refactor ingredient selection logic and fuzzy matching</li> <li>Update constraints for protein concentration limits</li> <li>Add nightly update checks with resource validation</li> </ul>	- Merge issue #94: Fan stays on after cooldown ends - Align fan off event with displayed countdown timer - Temp Control heat limit increased from 200 to 255

## Release Notes

Bugs Fixed	<ul> <li>Merge issue #211: Fix frozen app path resolution.</li> <li>Merge issue #207: Fix drop effect.</li> <li>Merge issue #204: Fix SQLite closed database errors.</li> <li>Merge issue #201: Optimize fill region analysis.</li> <li>Merge issue #197: Buffer concentration validation.</li> <li>Merge issue #196: Fix protein class field not persisting.</li> <li>Merge issue #186: Enhance serial and elaborate process</li> <li>Merge issue #180: Fix hourly background license refresh</li> <li>Merge issue #179: Fix protein class field stuck as none</li> <li>Merge issue #178: Fix temp control out-of-sync error.</li> <li>Merge issue #170: Hot fix for time index calculations.</li> <li>Merge issue #167: Fix Ch1 point window size too narrow</li> <li>Merge issue #166: Fix plot data out of sync during redraw</li> </ul>	- NONE
Known Issues	<ul> <li>Issue #227: Initialization temp check fails during tec cooldown.</li> <li>Issue #77 Export Functionality with preferences support</li> <li>Issue #47: Missing plate-config.json breaks ability to run device SW.</li> <li>Issue #45: Rename run on initial run info screen does not occur.</li> <li>Issue #21: FW update hangs on 'Failed to reboot' ERROR message.</li> </ul>	- NONE