

# Test Plan Execution Report

Test Project: EP\_PDK

Test Plan: PDK\_Test\_Plan\_01.10.00\_TDA2Ex\_17x17

Printed by TestLink on 28/06/2018

2017 (c) Testlink Community

### **Table Of Contents**

### 1.1.Examples

### 1.1.1.VPS Examples

#### 1.1.1.1.VPS Loopback Examples

```
pdk-tc-391: vps_examples_loopback_ov10635_vip_rgb888_dss_lcd
```

### 1.1.2.VSDK Examples

```
pdk-tc-1032: visionsdk_sch_fca_usecase
```

#### 1.2.MISC

```
pdk-tc-1034: pdk_build
```

pdk-tc-1035: pdk\_documentation

pdk-tc-1036: pdk\_non\_testable\_requirements

pdk-tc-1037: pdk\_customer\_application

## Test Project: EP\_PDK

Project: PDK Location: TII Owner: R, Sivaraj

## Test Plan: PDK\_Test\_Plan\_01.10.00\_TDA2Ex\_17x17

01.10.00 Test Plan for TDA2Ex\_17x17

## 1.1.Test Suite : Examples

## 1.1.1.Test Suite : VPS Examples

## 1.1.1.1.Test Suite: VPS Loopback Examples

Test Case pdk-tc-391: vps_examples_loopback_ov10635_vip_rgb888_dss_lcd				
<u>Summary:</u>				
OV1063x -> VIP1_S0/1_P	OV1063x -> VIP1_S0/1_PORTA (1280x720@30FPS) -> BGR888 -> DSS Video1 -> DPI1 LCD			
Preconditions: NA				
<u>#:</u>	Step actions:	Expected Results:	Execution notes:	
1	NA	Loopback image from input camera visible on LCD		
Execution type:	Manual			
Estimated exec. duration (sec):	60.00			
Priority:	Medium			
Test execution engine:				
Required hardware assets:				
Binary file name:				
DUT parameters:				
Test script or logic:				
Script Arguments:				
Test case time out [in sec]:				
Keywords:	c_sanity m_dss tda2ex tda2xx tda3xx tda2px t functional			
<b>Execution Details</b>	ion Details			
Build	PDK_Test_BUILI	D_01.10.00_TDA2Ex_17x17_rc6		
Tester	x0153534			
Execution Result:	Passed			
Execution Mode:	Manual			
Execution duration (sec):	xecution duration (sec):			

## 1.1.2.Test Suite : VSDK Examples

Test Case pdk-tc-1032: v	isionsd	c_sch_fca_usecase	
Summary:			
Vision SDK Single Ch From	Vision SDK Single Ch Front Camera Analytics Usecase		
Preconditions: NA	Preconditions:		
<u>#:</u>	Step actions:	Expected Results:	Execution notes:
1	NA	The thermal APIs are tested as part of limp home mode. One can switch successfully between limp home and normal mode. The overall power consumption is $\sim$ 2W.	
Execution type:	Manual		
Estimated exec. duration (sec):	30.00		
Priority:	Medium		
Test execution engine:			
Required hardware assets:			
Binary file name:			
DUT parameters:			
Test script or logic:			
Script Arguments:			
Test case time out [in sec]:			
Keywords:	c_full m_pm tda2ex tda2xx tda3xx tda2px t_functional		
<b>Execution Details</b>			
Build	PDK_Te	PDK_Test_BUILD_01.10.00_TDA2Ex_17x17_rc6	
Tester	x0153534		
Execution Result:	Passed		
Execution Mode:	Manual		
Execution duration (sec):	execution duration (sec):		

### 1.2.Test Suite: MISC

Summary:				
Daily and release build. Al	II requirements/is:	sues which are not testable but is part of the package and	is verified	
Preconditions: NA				
<u>#:</u>	Step actions:	Expected Results:	Execution notes:	
1	NA	Jenkin daily build and release build successful		
Execution type:	Manual			
Estimated exec. duration (sec):	30.00			
Priority:	Medium			
Test execution engine:				
Required hardware assets:				
Binary file name:				
DUT parameters:				
Test script or logic:				
Script Arguments:				
Test case time out [in sec]:				
<u>Keywords:</u>	c_sanity tda2ex tda2xx tda3xx tda2px t_functional m_common			
<b>Execution Details</b>				
Build	PDK_Test_BUIL	D_01.10.00_TDA2Ex_17x17_rc6		
Tester	x0153534			
Execution Result:	Passed			
Execution Mode:	Manual			
Execution duration (sec):				

Test Case pdk-tc-1035: pdk_documentation				
Summary:				
Verify that the PDK package	erify that the PDK package has latest release notes, API guide, datasheet, KW/MISRAC report, manifest and userguide			
Preconditions: NA				
<u>#:</u>	Step actions:	Expected Results:	Execution notes:	
1	NA	Verify the presence of these documents		
Execution type:	Manual			
Estimated exec. duration (sec):	30.00			
Priority:	Medium			
Test execution engine:				
Required hardware assets:				
Binary file name:				
DUT parameters:				

Test script or logic:	
Script Arguments:	
Test case time out [in sec]:	
Keywords:	c_sanity tda2ex tda2xx tda3xx tda2px t_functional m_common
<b>Execution Details</b>	
Build	PDK_Test_BUILD_01.10.00_TDA2Ex_17x17_rc6
Tester	x0153534
Execution Result:	Passed
Execution Mode:	Manual
Execution duration (sec):	

Test Case pdk-tc-1036: pdk_non_testable_requirements				
Summary:				
These are the non-testable requriements because of EVM or testup limitation				
Preconditions: NA	Preconditions:			
<u>#:</u>	Step actions:	Expected Results:	Execution notes:	
1	NA	No check need to be performed		
Execution type:	Manual			
Estimated exec. duration (sec):	30.00	30.00		
Priority:	Medium			
Test execution engine:				
Required hardware assets:				
Binary file name:				
DUT parameters:				
Test script or logic:				
Script Arguments:				
Test case time out [in sec]:				
Keywords:	c_sanity tda2ex tda2xx tda3xx tda2px t_functional m_common			
Execution Details				
Build	PDK_Test_BUILD_01.1	PDK_Test_BUILD_01.10.00_TDA2Ex_17x17_rc6		
Tester	x0153534			
Execution Result:	Passed			
Execution Mode:	Manual			
Execution duration (sec):	execution duration (sec):			

Test Case	pdk-tc-1037:	pdk_cus	tomer_ap	plication

Summary:

This test is to hold the requirements which are done specifically for a customers and tested in customer application

Preconditions:

NA

Execution type: Manual

Estimated exec. duration 20.00

<u>(sec):</u>	
Priority:	Medium
Test execution engine:	
Required hardware assets:	
Binary file name:	
DUT parameters:	
Test script or logic:	
Script Arguments:	
Test case time out [in sec]:	
Keywords:	c_sanity tda2ex tda2xx tda3xx tda2px m_common
<b>Execution Details</b>	
Build	PDK_Test_BUILD_01.10.00_TDA2Ex_17x17_rc6
Tester	x0153534
Execution Result:	Passed
Execution Mode:	Manual
Execution duration (sec):	