FLIGHT TRAINING EVALUATION RECORD


PILOT PERFORMANCE scorecard

TRAINEE PILOT	FLIGHT INSTRUCTOR (FI)	EVALUATION DATE
Ayush (QRV002)	**Instructor Ayush** (QRV001)	2026-06-07

50.0%

RETAKE REQUIRED
↓ Declined (-20.0%)

Communication		**33%**
Aircraft Handling		**100 %**
Systems & Procedures		**50%**
Ground Operations		**100 %**



CHECKLIST STATS

Passed Evaluated Checks	**3** / 6
Deficiencies (Errors)	**3**
Critical Deficiencies	**2**
Best Competency Area	**Aircraft Handling**
Primary Deficit Area	**Communication**

CRITICAL ITEMS REQUIRING REMEDIATION

- **Hold Short Announcement Procedure**: No, they didn't ■
- **Cruise Altitude Direction Procedure**: Incorrect cruise altitude selected for the flight direction■■

INSTRUCTOR OVERALL DEBRIEF & PERFORMANCE SUMMARY

A good flight overall, but needs to focus on UNICOM advisories and cruise altitude constraints. Landing and taxiing were excellent.

FLIGHT COMPETENCY DETAILED STATISTICS

COMPETENCY AREA	CHECKS EVALUATED	SCORE	RATING STATUS
Communication	1 / 3	33.3%	**CRITICAL**
Aircraft Handling	0 / 0	100.0%	**EXCELLENT**
Systems & Procedures	1 / 2	50.0%	**CRITICAL**
Ground Operations	1 / 1	100.0%	**EXCELLENT**

DETAILED PERFORMANCE FINDINGS BY FLIGHT PHASE

Review detailed compliance checks and specific corrective standards below.

PRE-FLIGHT

✓ **Passed:** **Main Switch Procedure**, **Flight Callsign Procedure**

TAXI

Taxi Announcement Procedure — MINOR DEFICIENCY

Issue Observed: There was significant gap between announcement and movement. ■■

Expected Standard: Trainee to announce Taxi before starting taxi.

Hold Short Announcement Procedure — CRITICAL DEFICIENCY

Issue Observed: No, they didn't ■

Expected Standard: Hold short should only be announced when another plane is taking off or landing on the runway

✓ **Passed:** **Hold Short Line Procedure**

CRUISE

Cruise Altitude Direction Procedure — CRITICAL DEFICIENCY

Issue Observed: Incorrect cruise altitude selected for the flight direction■■

Expected Standard: If plane is flying Eastbound flight then its Cruise Altitude should be in ODD numbers.

RECOMMENDED TRAINING MODULES & REMEDIATION

The training modules below have been dynamically generated based on checks requiring improvement.

1. Communication Procedures
- Taxi Announcement Procedure
- Hold Short Announcement Procedure

2. Flight Stabilization & Profiles
- Cruise Altitude Direction Procedure

EVALUATION REVIEW & APPROVAL

Following this simulator evaluation, the trainee's overall grading stands as **RETAKE REQUIRED**.

INSTRUCTOR SIGNATURE	TRAINING MANAGER REVIEW	DATE
.....	.....	.....