

PLANNED PREVENTIVE MAINTENANCE HOSPITAL TUANKU AZIZAH

YEAR: 2020

Update and verify inventory by checking and ticking boxes below

PPM:[/]Q1[]Q2[]Q3[]Q4

TYPE : [] Switch [] UPS [/] Firewall [] Load Balancer [] APs/Controller

Location: DC - RACK 2 Model: SuperMassive 9200

Manufacture: DELL

Serial Number: C0EAE4E53A3E

Hostname: FWUTM 01

Firmware Version: SonicOS Enhanced 6.2.7.1-23n

IP Address: 1.1.1.2 Mac Address:

A. PHYSICAL CHECK	
1.Cleaning	
a. Room	Yes
b. Rack	Yes
c. Equipment	Yes
2.Cable	
a. Tidiness	Yes
b. Labelling	Yes
3. Fan Condition	Yes
4. Check all LEDs and Port	Yes
5. Room Temperatur (Aircond)	
a. Temperature ()	Yes
6. Check UPS (Make sure UPS is connected properly and	Yes
functioning)	
7. PPM Tag	Yes
8. Device Tag	Yes
9. Power Over Ethernet	Yes
10. Free Port ()	Yes

B.SETTING & CONFIGURATION 1. Disable Unused Port Yes 2. Memory Utilization a. (Memory Utilization :) Yes 3. CPU Utilization a. (CPU Utilization:) Yes 4. Backup Configuration Yes 5. Check VLAN SNMP (String) a. (SNMP String :) Yes 6. Check VLAN Yes 7. HA Status a. Online Yes b. Standby Yes 8. Change Password Yes

C.FIREWALL

Able to manage firewall through a. (Unit management IP:) Able to manage unit through console port Connection Usage	Yes Yes
a. (Percentage :)	Yes
4. System Usage	.,
a. (System uptime :) 5. Check SNMP (String)	Yes
a. (SNMP String :)	Yes
6. VPN Status	.,
a. (Unique Firewall Identifier :) 7. Connection	Yes
a. (Peak: Yes) b. (Current:) c. (Max:)	Yes Yes Yes
C. (Max .)	162

i. App Control yes j. App Visualization k. WXAC Acceleration l. Botnet Yes	j. App Visualization k. WXAC Acceleration	Yes Yes
--	--	------------

D. UPS

- 1. Output Load ()
- 2. Battery Capacity ()
- 3. Battery Temperature ()
- 4. Run Time Remaining () 5. Replace Battery Indicator

E.LOAD BALANCER

- 1. Check system logs
- 2. Hard Disk Usage ()
- 3. Check System Memory

E. REMARK

Technical: FW okay and done

Prohawk: FW okay ITD :good job

SERVICED BY	VERIFIED BY	ENDORSED BY
Technical 18/03/2021	Prohawk Staff 18/03/2021	ITD staff 18/03/2021

NOTE: This PPM Form is computer generated and no signature is required