Property condition assessment / fictional training fixture

Harbor Loom Warehouse

A fictional low-rise, multi-tenant warehouse in East Boston.

Report date: October 24, 2026.

The building was constructed in 1979.

Purpose and scope

This report is a synthetic document written solely to test evidence extraction, missing-field handling, and allocation scenarios. Harbor Loom Warehouse is not a real property. No site visit, owner interview, inspection or contractor pricing occurred.

Scope is a fictional visual roof-condition review and an illustrative capital reserve allowance. Building construction date is contextual information only and is not evidence of roof age.

Information supplied

The source packet describes a low-rise warehouse with multiple leased spaces. No roofing installation records were supplied. Historic reroofing dates, warranty records and membrane age remain unknown.

Read the roof findings on page 2 together with the structural and metering limitations on page 3. A favorable financial scenario does not establish feasibility.

Roof findings / synthetic observations and budget

A near-term roof decision

Roof type: low-slope modified-bitumen membrane.

Remaining useful life is estimated at 2 to 4 years.

Estimated roof replacement cost: $300,000 (2024 dollars).

The fictional observations are localized ponding, patched seams and weathered flashing. The remaining-life range is an illustrative planning judgment, not a guarantee against leaks or a measured service life.

Planning allowance

The $300,000 synthetic replacement allowance represents one roof replacement and includes an assumed general removal and replacement scope. It is not a contractor quote; hazardous materials, hidden damage, code upgrades and structural reinforcement are not priced.

Timing for the demonstration

Year 3 is the selected planning scenario within the 2-to-4-year range. The range remains the extracted evidence; year 3 is a separate human-selected assumption. Do not replace a range with an invented exact observation.

For solar installed before replacement, the separate model assumes $75,000 for panel removal and reinstallation and 5% production downtime in the replacement year. Those assumptions are not included in the $300,000 roof allowance and are not inspection findings.

Budget figures use constant 2024 dollars for consistency with the model cost anchors. No escalation or incentives are included.

Limitations / tenant electricity arrangements

What this report cannot establish

Structural capacity for rooftop equipment was not assessed.

A qualified professional must assess structural capacity, attachments, wind loads and roof compatibility before any rooftop equipment decision. This report is not structural approval, a solar design, or a building-code compliance determination.

Tenants are separately metered and pay their electricity bills.

The separate-meter arrangement is synthetic. Utility territory, supplier, tariff class, tenant account identifiers, lease terms and permission to allocate credits were not reviewed. No executed credit-allocation agreement is asserted.

Missing evidence

No roofing installation records were supplied.

Roof age remains unknown. The building construction date does not resolve it. Obtain original records, warranty documents and a professional roof review before relying on any age-based estimate.

Use with the demonstration model

All financial outcomes are conditional on assumed eligible electricity value, solar production, capital costs, operating costs and allocation terms. The model assumes no rent increase or new tenant charges. It does not determine legal or utility eligibility.

SMART, 48E and BERDO may change the result. No incentive, tax credit, penalty avoidance, structural approval or real-property recommendation is provided by this fixture.