# 第一个STC89C52项目(密码锁)

### 工具:

这里可以用的语言有C, C++还有汇编, 我用的是对于初学者比较友好的C语言。


编译软件我用的是Keil uVision5, 烧录用的是STC—ISP。

本博客只提供了部分代码,如果需要完整代码请前往\*钦某/51project - 码云 - 开源中国 (gitee.com)\*

### 函数及模块:

#### 1.延迟函数Delay

可以直接从STC—ISP上的软件延时计算器上拷贝



编辑

但是我这里用的Delay是根据b站上的up主修改过的,可以随意定义要延迟的时间,非常好用!

```
void Delay(unsigned int xms)
{
```

```
unsigned char i, j;
while(xms--)
{
    i = 2;
    j = 239;
    do
    {
        while (--j);
    } while (--i);
}
```

### 2.液晶屏 (LCD1602) 显示模块

这个模块定义了许多函数,我们可以使用这些函数让屏幕上显示我们所需要的参数,这让我们在调试程序的时候更加方便直观。非常好用!

```
#ifndef __LCD1602_H__
#define __LCD1602_H__

//用户调用函数:
void LCD_Init();
void LCD_ShowChar(unsigned char Line,unsigned char Column,char Char);
void LCD_ShowString(unsigned char Line,unsigned char Column,char *String);
void LCD_ShowNum(unsigned char Line,unsigned char Column,unsigned int
Number,unsigned char Length);
void LCD_ShowSignedNum(unsigned char Line,unsigned char Column,int Number,unsigned char Length);
void LCD_ShowHexNum(unsigned char Line,unsigned char Column,unsigned int
Number,unsigned char Length);
void LCD_ShowBinNum(unsigned char Line,unsigned char Column,unsigned int
Number,unsigned char Length);
#endif
```

### 3.矩阵键盘函数 (MatrixKey)

将这个函数放入while (1) 循环里就可以不断对矩阵键盘的8个I/O口进行扫描,如过按下某个键,此函数将会返回所对应的数值。非常好用!

```
#include <REGX52.H>
#include "Delay.h"
unsigned char MatrixKey()
{
   unsigned char KeyNumber=0;
```

```
P1=0xFF:
    P1_3=0;
    if(P1_7==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=1;}
    if(P1 6==0){Delay(100); while(P1 7==0); Delay(100); KeyNumber=5;}
    if(P1 5==0){Delay(100); while(P1 7==0); Delay(100); KeyNumber=9;}
    if(P1_4==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=13;}
    P1=0xFF:
    P1 2=0;
    if(P1_7==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=2;}
    if(P1_6==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=6;}
    if(P1_5==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=10;}
    if(P1_4==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=14;}
    P1=0xFF;
    P1_1=0;
    if(P1 7==0){Delay(100); while(P1 7==0); Delay(100); KeyNumber=3;}
    if(P1 6==0){Delay(100); while(P1 7==0); Delay(100); KeyNumber=7;}
    if(P1_5==0){Delay(100)}; while(P1_7==0); Delay(100); KeyNumber=11;}
    if(P1_4==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=15;}
    P1=0xFF;
    P1_0=0;
    if(P1_7==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=4;}
    if(P1_6==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=8;}
    if(P1_5==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=12;}
    if(P1_4==0){Delay(100); while(P1_7==0); Delay(100); KeyNumber=16;}
    return KeyNumber;
}
```

声明:此函数是作者跟着江协科技up主写的,可能还有其它实现办法,但是相对来说这可能是最浅显易懂的一种方法。

### 主函数:

```
#include <REGX52.H>
#include "Delay.h"
#include "LCD1602.h"
#include "MatrixKey.h"
#define password 2345 //初始密码

unsigned char KeyNum;
unsigned int Password,count;

void main()
{
```

```
LCD_Init();
   LCD_ShowString(1,1,"Password:");
   while(1)
       KeyNum=MatrixKey();
       if(KeyNum)
           if(KeyNum<=10&&count<4)//s1-s10对等1 2 3 4 5 6 7 8 9 0
           {
                   Password*=10; //CSDN回文对称 http://t.csdnimg.cn/4cN6e
                   Password+=KeyNum%10;//获取密码
                   count++;
                                                                 //计次加一
                   LCD_ShowNum(2,1,Password,4);
           if(KeyNum==11) //将s11设置成确认键
               if(Password==password)
                   LCD_ShowString(1,11,"True ");
                   Password = 0;
                   count = 0;
                                       //清零
                   LCD_ShowNum(2,1,Password,4);
               }
               else
               {
                   LCD_ShowString(1,11,"False");
                   Password = 0;
                                       //清零
                                              //清零
                   count = 0;
                   LCD_ShowNum(2,1,Password,4);
               }
           if(KeyNum==12) //将s12设置为取消键
               Password = ∅;
                                        //清零
               count = 0;
                                      //清零
               LCD_ShowNum(2,1,Password,4);
           }
       }
   }
}
```

\*\*I.\*\*首先在主函数前面要包含一系列的头文件。

因为我们在做的是一个密码锁,那么就要有正确的密码,这里我把密码设置成4位,直接宏定义password方便修改。

\*\*II.\*\*然后我们来到main函数里面。

LCD\_Init();对LCD1602进行初始化,LCD\_ShowString(1,1,"Password:");让Password:显示在屏幕的第一排第一列

\*\*III.\*\*之后是我们的重头戏循环,我们要不间断的对键盘进行扫描:while (1)。定义一个KeyNum来接收MatrixKey()返回来的值并进行判断,如果KeyNum非0,进入到第一个if里面。

\*\*IV.\*\*我们将s1到s9设置为所对应的数字, s10设置为数字0, s11为确认, s12为取消。

第二个if判断了反回来的KeyNum范围在10以内,由于只有4位密码,为了防止多输入,我们再在外面定义一个计数器count默认值位0。并在第二个if同时判断count。在第二个if里面的代码在作者往期的博客里面有类似的,这里就不解释了。(详情:CSDN回文对称 http://t.csdnimg.cn/4cN6e)

\*\*V.\*\*第三个if语句里面对按键s11进行了定义。

判断输入的密码是否和定义的密码相等,如果相等在LCD上显示"真" LCD\_ShowString(1,11,"True ")否则显示"假" LCD\_ShowString(1,11,"False")。 (注意这里True比False少一个字母,应该在True后面加一个空格才能保证能把 False全部覆盖掉。) 之后将Password和count归零。


声明:这里除了让屏幕显示真假,还可以写一些函数代码让外部电机转动以此来实现物理上的开关

\*\*VI.\*\*第五个if语句定义了按键s12

当KeyNum等于12时将Password和count归零。

## 总结:

这个项目需要我们对单片机的各个外设有一定的认识并懂得使用,总的来说代码较为简单,逻辑比较复杂。随着对C语言和单片机学习的不断深入,我对计算机的底层逻辑的认识越来越清晰,



编辑

如果有什么错误,欢迎指出,如果有帮助,点个赞,谢谢。