


(a) Gain saturation $g = g_0/(1 + I/I_{\text{sat}})$



(b) Gain clamping above threshold

