```
***** Read Me First ****

**** Read Me First ****
```

Version: 2.2.2.0 Oct 2020

Introducing the AgB29xx IVI Driver for the Keysight B29xx family of instruments

\_\_\_\_\_\_

This instrument driver provides access to the functionality of the B2901A, B2902A, B2911A, B2912A, B2961A and B2962A through a COM server or ANSI C API which also complies

with the IVI specifications. This driver works in any development environment which supports COM or C programming including Microsoft Visual C++, Microsoft .NET, Keysight VEE Pro, National Instruments LabView, LabWindows CVI, MATLAB(32 bit only) and others.

# Supported Instruments

-----

B2901A

B2902A

B2911A

B2912A

B2961A

B2962A B2901B

B2901BL

B2902B

B2910BL

B2911B

B2912B

B2961B

B2962B

## Installation

-----

System Requirements: The driver installation will check for the following requirements. If not found, the installer will either abort, warn, or install the required component as appropriate.

Supported Operating Systems:

Windows 7 32-bit, 64-bit

Windows 8 32-bit, 64-bit

Windows 10 32-bit, 64-bit

## **Shared Components**

Before this driver can be installed, your computer must already have: IVI Shared Components Version: 2.6.1 or newer installed

The IVI Shared Components installers are available from: http://www.ivifoundation.org/shared components/Default.aspx

### VISA-COM

Any compliant implementation is acceptable. Typically, VISA-COM is installed with VISA and other I/O library modules. The latest version of Keysight's IO Libraries is recommended and includes VISA-COM.

You can download the latest version from:

http://www.keysight.com/find/iosuite

### Uninstall

-----

This driver can be uninstalled like any other software from the Control Panel

using "Add or Remove Programs" or "Programs and Features" dialog.

The IVI Shared Components may also be uninstalled like any other software from the Control Panel using the "Add or Remove Programs" or "Program & Features" dialog.

Note: All IVI-COM/C drivers require the IVI Shared Components to function. To completely remove IVI components from your computer, uninstall all drivers and then uninstall the IVI Shared Components.

### Source Code

### ------

Driver source code is available by enabling the "Source Code" option in the "Custom Setup" dialog when installing the driver. This code is provided as is for informational purposes only. Modification of this code is not supported. Code is a Visual Studio 2010 C++ project and may be updated to new versions of Visual Studio.

Caution: Once you have installed version 2.x of the IVI Shared Components, you will not be able to build IVI drivers and applications developed with earlier versions. You will need to upgrade those drivers/applications to the new IVI Shared Components and to build on Visual Studio 2010 or higher or you will need to build those drivers/applications on a different machine that does not have version 2.x of the IVI Shared Components.

### Start Menu Help File

### -----

A shortcut to the driver help file is added to the Start Menu, All Programs, Keysight Instrument Drivers, IVI-COM-C Drivers, KtIviComDrvr group. It contains "Getting Started" information on using the driver in a variety of programming environments as well as documentation on IVI and instrument specific methods and properties.

You will also see shortcuts to the Readme and Introduction files and programming examples for this driver.

## Additional Setup

### .NET Framework

The .NET Framework itself is not required by this driver. If you plan to use the driver with .NET, the minimal .NET framework version is:  $2.0\,$ 

The .NET Framework requires an interop assembly for a COM server. A Primary Interop Assembly, along with an XML file for IntelliSense is installed with the driver. The driver's PIA along with IVI PIAs are installed by default in: drive:\<Program Files>\IVI Foundation\IVI\Bin\Primary Interop Assemblies

The PIA is also installed into the Global Assembly Cache (GAC) if you have the .NET framework installed.

### Using a New Version of the Driver

### -----

New versions of this Keysight IVI-COM/C driver may have a new ProgId.

If you use the version dependent ProgId in CoCreateInstance, you will need to modify and recompile your code to use the new ProgID once you upgrade to the next version of the driver. Doing a side-by-side installation of the driver to use multiple versions of the driver is not supported. If you need to go back to an older version of the driver, you need to uninstall the later version and install the older version.

If you use the version independent ProgId in CoCreateInstance, you will not

need to modify and recompile your code. The new version of the driver has been tested to be backwards compatible with previous versions.

To access the new functionality in a new version of the driver you will need to use the latest numbered IKtIviComDrvr[n] interface rather than the IKtIviComDrvr interface. The IKtIviComDrvr[n].<interface> property will return a pointer to the new IKtIviComDrvr<interface>[n] interface. The IKtIviComDrvr<interface>[n] interface contains the methods and properties for the new functionality and inherits all prior interface functionality. The new interfaces were introduced rather than modifying the existing interfaces for backwards compatibility. The interfaces that were previously shipped have not been changed.

Pre-existing .NET client applications must be re-build before using the new version of the driver.

## Revision History

------Version Date Notes --------------2.2.2.0 Sep 2020 Added model support for B2901B, B2901BL, B2902B, B2910BL, B2911B, B2912B, B2961B, B2962B. Fixed customer reported defect. 2.1.1.0 Jun 2018 2.1.0.0 Mar 2015 Updated help file, added IVI-2014 Compliance, Rebranded Keysight Technologies 2.0.5.0 Nov 2012 Enhanced driver to support B296x family of instruments 1.0.7.0 June 2011 IviDCPwr class support added for IVI C driver also Initial release 1.0.6.0 June 2011

### IVI Compliance

-----

IVI-COM/IVI-C IviDCPwr Specific Instrument Driver

IVI Generation: IVI-2014
IVI Instrument Class: IviDCPwr

IviDCPwr Spec: IVI-4.4 Revision: 3.0

Group Capabilities Supported:

IviDCPwrBaseYesIviDCPwrTriggerYesIviDCPwrSoftwareTriggerYesIviDCPwrMeasurementYes

Optional Features:

Interchangeability Checking No State Caching No Coercion Recording No

Driver Identification:

Vendor: Keysight Technologies

Description: AgB29xx Arbitrary Waveform Generator

Revision: 2.2.2.0

Component Identifier: AgB29xx.AgB29xx

Hardware Information:

Instrument Manufacturer: Keysight Technologies

Supported Instrument Models: B2901A, B2902A, B2911A, B2912A, B2961A, B2962A

Supported Bus Interfaces: TCPIP, GPIB

32-bit Software Information:

Supported Operating Systems: Windows 7 32-bit, Windows 8 32-bit, Windows 10 32-bit

Unsupported Operating System: Windows 2000 Support Software Required: VISA-COM

Source Code Availability: Source code included with driver via custom installation option.

### 10/25/21, 10:48 PM

64-bit Software Information:

Supported Operating Systems: Windows 7 64-bit, Windows 8 64-bit, Windows 10 64-bit

Support Software Required: VISA-COM

Source Code Availability: Source code included with driver via custom installation option.

# Unit Testing

-----

Test Setup Instrument:

Instrument Models (FW Revision): B2912B (5.0.2029.1911)

Bus Interface: TCPIP
Operating System (Service Pack): Windows 10
OS Bitness/Application Bitness: 64-bit/32-bit

VISA Vendor and Version: Keysight VISA-COM (IO Libraries 18.1)

IVI Shared Components Version: 2.6.1

Test Setup Simulation:

Instrument Models: (FW Rev N/A) B2912B Bus Interface: N/A

Operating System (Service Pack): Windows 7 (SP1)

OS Bitness/Application Bitness: 64-bit/32-bit, 64-bit/64-bit

VISA Vendor and Version: N/A
IVI Shared Components Version: 2.6.1

Driver Installation Testing:

Operating System (Service Pack): Windows 7 (SP1), Windows 8, Windows 10

OS Bitness: 32-bit, 64-bit

Driver Buildability:

Operating System (Service Pack): Windows 7 (SP1), Windows 8, Windows 10

OS Bitness: 32-bit, 64-bit

Visual Studio Version: VS2010

Driver Test Failures - Known Issues:

None - This driver does not have any known defects.

Keysight Technologies has evaluated and tested this driver to verify that it meets all applicable requirements of the IVI specifications at the time this compliance document was submitted to the IVI Foundation and agrees to abide by the dispute arbitration provisions in Section 7 of IVI-1.2: Operating Procedures, if the IVI Foundation finds this driver to be non-conformant.

## More Information

-----

For more information about this driver and other instrument drivers and software available from Keysight Technologies visit:

http://www.keysight.com/find/drivers

A list of contact information is available from:

http://www.keysight.com/find/contactus

Microsoft, Windows, MS Windows, and Windows NT are U.S. registered trademarks of Microsoft Corporation.

Copyright Keysight Technologies 2020