DIGI-LOGS DEMO MAINTENANCE GUIDE

DEMO / SYNTHETIC DOCUMENT - NOT AN OFFICIAL OKUMA MANUAL

Machine ID: CNC-003

Asset Code: ASSET-CNC-003

Manufacturer: OKUMA

Series: GENOS

Model: M560-V

Purpose:

This document is synthetic demo data for Digi-Logs.

It is used to test PDF ingestion, retrieval and citation.

Demo Maintenance Case - Spindle Vibration

Symptom:

Abnormal vibration occurs when the spindle runs at high speed.

Possible cause:

Spindle belt tension may be below the expected operating range.

Recommended inspection:

1. Stop the machine safely.
2. Inspect spindle belt condition.
3. Verify belt tension.
4. Adjust belt tension if required.
5. Run a controlled verification test.

Expected result:

Spindle vibration returns to the normal baseline after adjustment.

Safety note:

This is synthetic demonstration content for Digi-Logs testing.