

INSPECTION REPORT IR-2026-0160

Equipment: 6"-P-1045-A1B Crude overhead line downstream of wash water injection

Unit: Crude Distillation Unit 1

Inspection date: 02-Jun-2026 **Previous inspection:** 05-Jun-2023

Inspector: A. Rao (synthetic)

Thickness readings (UT), interval 3.0 years

CML	Location	t prev (mm)	t actual (mm)	t min (mm)	CR (mm/yr)	RL (yr)
C1	Injection point +300 mm	7.1	5.9	3.4	0.400	6.3
C2	Elbow E-4	7.1	5.6	3.4	0.500	4.4
C3	10D downstream	7.1	6.5	3.4	0.200	15.5

Findings

1. Elbow E-4 shows the highest corrosion rate, consistent with ammonium chloride under-deposit corrosion.

Recommendation

Corrosion rate exceeds 0.25 mm/year at two CMLs: propose material upgrade review per STD-ENG-110.
Increase monitoring of elbow E-4 to annual.