

INSPECTION REPORT IR-2026-0155

Equipment: P-1201B Crude charge pump casing

Unit: Crude Distillation Unit 1

Inspection date: 14-Jul-2026 **Previous inspection:** 10-Jul-2023

Inspector: K. Shetty (synthetic)

Thickness readings (UT), interval 3.0 years

CML	Location	t prev (mm)	t actual (mm)	t min (mm)	CR (mm/yr)	RL (yr)
C1	Casing volute	22.0	21.1	17.0	0.300	13.7
C2	Suction nozzle	14.0	13.2	9.5	0.267	13.9

Findings

1. Erosion marks at the volute tongue. Mechanical seal leaking at 5 drops per minute.

Recommendation

Replace mechanical seal per SOP-MNT-050. Re-measure casing in 3 years.