
(a)
(b)
Eq. (3): B, C from fit
Eq. (5): log decrement δ
Quality factor Q
1/Q
Residual
Overlap area A_ov (mm²)
Overlap area A_ov (mm²)