



$\omega^* = 0.10$, meas = 0.03, err = 74.9%




$\omega^* = 0.30$, meas = 0.03, err = 91.6%




$\omega^* = 0.50$, meas = 0.52, err = 4.9%




$\omega^* = 0.70$, meas = 0.73, err = 3.9%




$\omega^* = 1.00$, meas = 1.02, err = 1.6%




$\omega^* = 1.50$, meas = 1.50, err = 0.2%



$\omega^* = 2.00$, meas = 1.93, err = 3.7%



$\omega^* = 2.15$, meas = 2.11, err = 1.8%



t

t