

Second Law of Thermodynamics

1. Second Law of Thermodynamics

Statement: It is impossible to transfer total heat into work in a cyclic process in the absence of other effect (by Lord Kelvin).

In another way it is also stated that it is impossible for heat to be transferred by a cyclic process from a body to one warmer than itself without producing other changes at same time.