

Approved by	Checked by	Prepared by
Kato Shunichi		Nhu Dinh Duy

FLOW TO CHECKING FA SAMPLE ,RULE TO KEEKPING

Confidential : Canon internal use only

LBP Material Quality Assurance	Issued No LBPMQA-FA-037	Revision 01
--------------------------------	----------------------------	----------------

THE RULE TO KEEP FA SAMP

1- LAY OUT


- * Keeping FA sample in 2nd floor
- * Have to indicate by colour tape f

2- TIME TO KEEP FA SAMPLE

- * With part of MO, PX, AL, AS, ... : Keep FA sample until stop model (after that Manager decide)
- * Packing part : Keeping until finish MT

3- KEEPING METHOD

- * Keeping : Min 2 pcs / cavity
- * Use nilon bag for package
- * Keeping FA sample together with FA report .
- * Paste control sheet on outside box .
- (On the sheet have Control No , Model)
- * Keep FA sample on the end off week
- * FA report keep in the Bander and scan save o



4- DISPOSAL METHOD

- * For MO part, PX part, Al part, AS part, ... : to classify part by Grade, type of Material and then, move it to the rubbish store
- * For Packing part : break the part before move to the rubbish store

5- CONTROL METHOD

- * Input all information of FA sample on the PC (Part No, Die No, Ver, Maker, Sub No, box No ...)

Note: - When you want to see FA sample pls inform to FA member (Ms Qùynh, Ms Ngoc, Ms Anh)

Time : on 10h a.m or 3h p.m

- When borrow FA sample, Pls fill all information in " Control borrowing of FA sample "

[illegible]

[illegible]