






5V 3A BUCK CONVERTER LM2596S U5 LM2596S-5 TestPoint ~3A OUTPUT power_inputD-C110A106MA8NRN C324 T00u C38 C322 -- Dpower_output_5v_3A 47uH C39 330u D4 SS54 VP1C331M0607 TP7 TestPoint GND GND GND GND Sheet: /5V_2A_BUCK_BOOST/ File: 5V_2A_BUCK_BOOST.kicad_sch Title: Size: A4 Date: Rev: KiCad E.D.A. kicad 7.0.2 ld: 6/17






























LITHIUM BATTERY CHARGER



Sheet: /bat_charger/
File: bat_charger.kicad_sch

Title:

 Size: A4
 Date:
 Rev:

 KiCad E.D.A. kicad 7.0.2
 Id: 18/17