# MURA DEFECTS 8000series





# MURA PANELS CUSED BY REFLECTOR

MODEL PCS 50PUS8009/12 30 50PUS8139/60 16 50PUS8079/12 14 50PUS8009/05 12 65PUS8959/12 55PUS8079/12

The problem occurs in large inches

# TOP TV MODELS





# Types of Mura defects

# SIDE MURA






#### **CHECK VIDEO ->**

#### Caused By:

- Incorrectly mounted LEDs
- Incorrectly mounted headlight
- Deformed B/L
- REPAIRABLE





# CORNER MURA





#### Caused By:


- Incorrectly mounted LEDs
- Incorrectly mounted headlight
- Deformed B/L
- REPAIRABLE








### LED BAR MURA





#### **CHECK VIDEO ->**

#### Caused by:


- Incorrectly mounted LEDs
- Damage BLU cable
- Damage connector
- Incorrectly mounted headlight
- Deformed B / L
- REPAIRABLE





# LED / LENS MURA








#### Caused by:


- Incorrectly mounted LEDs
- Incorrectly mounted headlight
- Deformed B / L
- REPAIRABLE





### **WAVE MURA**






#### **CHECK VIDEO ->**

#### Caused By:

- Incorrectly mounted Films
- Deformed B / L
- Deformed FC
- REPAIRABLE






### DIFFUSER PLATE MURA








- Dirt under or upper Diffusor plate
- **REPAIRABLE**







# Mura repair methods

# Methods of Repair



#### 1. Reassembly and Uniform Pressure Calibration:

- Loosen and retighten all bezel/frame screws evenly
- Apply symmetric pressure (manual or torque-limited)
- Slightly reducing pressure on one side often improves bleed

#### 2. Check and Reposition Optical Components:

- Inspect the diffuser, reflector, and prism sheets
- Ensure they are clean, flat, and correctly aligned
- Avoid tight cuts that cause bending

#### **3**. Cleaning Optical and Edge Surfaces:

- Use gloves and anti-static tweezers
- Remove dust, fibers, or glue residue
- Check for particles between diffuser and panel layers

#### **4**. Modify or Replace Rubber Gaskets:

- Use soft foam spacers to apply even pressure
- Replace hardened or deformed rubber parts

#### **5**. Check and Reposition LED BAR:

- Ensure LEDs are not overheated (yellow = degraded phosphor)
- Align LED lenses and keep proper distance from diffuser









Service Tips - Always test after each step (black screen + test bars) - Use a dark room or test booth for visual clarity - Document 'before/after' results with photos

# Mura repair methods




#### Adjusting the Mura primarily depends on the cause of the defect


Correct bending of the reflector, correct assembly of films without bends, correctly cleaned diffuser, films, no backlight defects that can create "mura"

Correctly mounted headlight, Film











correctly assembly middleframe, middle frame etc.





# THANK YOU!