




POSTER PRESENTATION ON MINITAB USAGE









Histogram

Scatterplot


Pie Chart






cause & effect diagram

Boxplot





Pareto Chart

ANOVA

USAGE OF MINITAB Here Minitab is used for various statistical data analysis. From Histogram to ANOVA including Boxplot, Pie and Pareto chart, Bubble Plot, Scatterplot etc all of these are plotted here by

means of MINITAB

Missing button	52	0.17	36.89
Loose thread	21	0.89	59.63
Misaligned fabric	18	5.12	92.16
Fabric flaws	23	4.89	112.47
Stitching errors	112	1.89	211.68
Hemming errors	43	4.23	181.89
Hydrogen	Porosity	Strength	
0.180000	0.500150	0.83931	
0.210000	0.410000	1.12253	
0.210000	0.450000	1.11309	
0.210000	0.550000	1.10000	
0.220000	0.440000	0.70705	
0.220000	0.240000	0.49751	
0.230000	0.470000	0.53000	
0.230000	0.700000	0.52062	
0.240000	0.800000	0.19287	
0.240000	0.220000	0.54000	
0.250000	0.880000	0.39086	
0.260000	0.720000	0.42000	
0.270000	0.750000	0.18348	
0.280000	0.700000	0.24000	
A .			

Contact

Kazi Arman Ahmed Rahat Roll:201636052

Level: 03

Department of Industrial and Production Military Institute of Science and Technology