





Technical Report

TR150563

28-Nov.-2017

From:

Canez Power Division S.A.

Electrical Motor- Rewinding Section

+509 2811 3669

team@canezgeneration.com

To:

Brasserie National D'Haiti S.A

Tel: +509 3701 0134

Adulex.blemur@heinken.com

1. Motor Receive.

Date In:	Nov.28 th 2018
Description:	Compressor (25hp)
Fault:	Need to rewire cause it burned
Delivery	Jan.11 th 2018

2. Repair

Opening process



Received



Difficulties to open



stator burned



Inside

Repair Process



Ready to rewire



Rewinding



From the Oven



Parts cleaned



Ready

3. Final Comments

Received it complete, after dissembling find it burned then started rewinding, put it in oven, cleaned parts, added 2glls oil of tractor and sent it to Brana for testing.

4. Warranty Tag

- 15153
- 90 days warranty