





Technical Report

TR150571 19-Feb.-2018

From:	To:

Canez Power Division S.A. **Electrical Motor- Rewinding Section** +509 2811 3669

team@canezgeneration.com

Brasserie National D'Haiti S.A Tel: +509 3701 0134 Adulex.blemur@heinken.com

1. Motor Receive.

Date In:	Feb.19 th 2018	
Description:	1 Electrical Motor (15 HP)	
Fault:	Need to rewire cause it burned .	
Delivery	Feb.23 rd 2018 by wandy team	

2. Repair

Opening process





Bearings Issue

Stator burned

Repair Process











Stator ready

Rewinding

Oven

Bearings changed Rrady

3. Final Comments

Received this electrical motor complete, need to rewire cause it burned, then came back here at the for two times for connection issue. Job done: rewinding, both bearings changed and painted.

4. Warranty Tag

- 15162
- 90 days warranty

Technical Report