


GND

N64 Edge Connector



Do not solder Q1 if D2 is soldered. Use either D2 or Q1. Do not solder R1 and R6.

