

- 2. Cross BTY at the assigned ATC altitude; proceed outbound on the BTY R-096 direct JAYSN
  3. Cross JAYSN and continue outbound on the BTY R-096 to STRYK

  4. Expect clearance for STRYK Pacovery during daytime/when VMC and traffic permits.
- Cross JAYSN and continue outbound on the BTY R-096 to STRYK
   Expect clearance for STRYK Recovery during daytime/when VMC and traffic permits
   STRYK Recovery clearance authorizes descent to cross STRYK at or above 9,500 feet MSL