

RWY 03 overhead PFO authorized during IFE conditions only.

- Day only (Sunrise to Sunset).
- 3. Weather Requirements: Ceiling 1K above highest altitude to be flown/5 NM visibility
- 4. Request PFO with NATCF or Tower.
- Holding: Hold VFR at Dry Lake between 9,500 feet to 11,500 feet MSL, left turns.
- Breakout Instructions:

a. Overhead: Descend to 4K MSL, proceed direct FLEX/comply with FLEX reentry b. SI-PFO: Return to Dry Lake prior to 10 DME/as instructed by ATC inside 10 DME

OVERHEAD PFO:

- Add desired altitude with high key request.
- Maximum high key altitude 14,000 feet MSL.

3. Report "High Key," "Low Key" and "Base, gear down, low approach."

STRAIGHT-IN PFO:

- If cleared by NATCF, proceed to 10 DME final.
- Report position and altitude to Tower on contact.
- Cross 10 DME between 9,500 feet and 11,500 feet MSL.
- Report "BOLT 1, 10 mile precautionary flame-out final." Cross 5 DME between 7,000 feet and 10,000 feet MSL.
- Report "BOLT 1, 5 mile precautionary flame-out final, gear down, low approach."