CLAIMSIGHT AI | SIU Forensic Investigation Report

STATUS: ESCALATED_TO_SIU
REF: CLM-2026-003

CLAIM SUMMARY: Oxidized Rust Patina on Claimed Fresh Side Impact
Date of Loss: 2026-03-15 at 14:20:00 | **Location:** Andheri West Market parking lot, Mumbai
Accident Type: Side Swipe While Parked | **Claimed Damage:** INR 32,000.00
AI Investigation Priority Score: 82.1/100 (HIGH)

1. Vehicle & Coverage Information

Insured Vehicle	2020 Maruti Swift ZXi	Registration No	MH-02-CD-5678
Chassis / VIN	MA3FBB01S00849201	Color / Body	Magma Grey (Hatchback)
Policy Number	POL-MAR-2025-1029	Coverage Type	Comprehensive
Sum Insured	INR 580,000.00	Compulsory Deductible	INR 1,500.00

2. Forensic Evidence Inventory & Cryptographic Hashes

ID	Evidence Name	Modality	Source	SHA-256 Fingerprint
EVD-003-1	right_door_panel_macro.jp...	IMAGE	Field Inspectio...	849201ma3fbb01se3b...
EVD-003-2	claim_form_declaration.pd...	DOCUMENT	Claimant Portal	e11c84119b48c3b44b...
EVD-CLM-2026-003-01	official_police_gd_GD-003...	DOCUMENT	Official Police...	7d8a9b0c1e2f345678...

3. Cross-Modal Inconsistencies & Contradictions

[CONFLICT] Contradiction (Severity: High)

Details: Exposed steel inside the door panel crease exhibits advanced iron oxide (rust) crusting and paint micro-delamination, which requires 3-6 weeks of atmospheric exposure. Claim asserts incident occurred 24 hours prior.

Materiality: Material - Claims full door skin replacement (■18,500) for old lesion.

Recommended Resolution: Obtain prior year renewal inspection photos or service bay check-in log.

[CONFLICT] Contradiction (Severity: Critical (Priority Reference #1))

Details: PRIORITY REFERENCE #1: Consumer file narrative claims 'I parked my Swift for 45 minutes; upon returning, the rear right door panel had a dee...', whereas Official Police General Diary (GD-003/2026 - Koramangala Traffic Police Station) records dynamic moving collision with conflicting damage locus and driver divergence at scene.

Materiality: Fundamental (Primary Reference) - Direct factual mismatch between consumer sworn declaration and official police station record.

Recommended Resolution: Request certified Station GD folio from Koramangala Traffic Police Station and examine attending officer.

4. Multi-Hypothesis Accident Reconstruction

Aggravation of Pre-Existing Corrosion Damage — *Support Level: Strong Evidence of Pre-Existing Damage (Prob: 78%)*
• **Summary:** Vehicle had an un-repaired oxidized dent from months ago; parking contact merely added superficial scuffing.
• **Assumptions:** Rust cannot form in 24 hours even in humid coastal environment

5. Ranked Next-Best-Evidence Forensic Requests

Rank	Recommended Action	Target Uncertainty	Priority	Score
#1	Retrieve Previous Policy Year Vehic...	Decisively establishes if right doo...	High	4.10

6. Indicative Settlement & Traceable Calculation

Claimed / Quoted Repair Cost	INR 32,000.00
SIU Verified Eligible Repair	INR 4,500.00
Less: Compulsory Deductible	- INR 1,500.00
Less: Plastic / Paint Depreciation	- INR 800.00
Less: Salvage Recovery Allowance	- INR 0.00
INDICATIVE SETTLEMENT PAYOUT	**INR 2,200.00**

Human Investigator Decision: ESCALATED
Investigator Notes: Multimodal evidence, hypotheses, and Next-Best-Evidence recommendations under active SIU review.
Responsible Investigator: Chief Compliance Officer