CLAIMSIGHT AI | SIU Forensic Investigation Report

STATUS:
AWAITING_EVIDENCE
REF: CLM-2026-006

CLAIM SUMMARY: Unitemized Lump-Sum Repair Estimate Submitted
Date of Loss: 2026-03-11 at 08:15:00 | **Location:** DND Flyway, Delhi-Noida
Accident Type: Front Grille & Sensor Impact | **Claimed Damage:** INR 145,000.00
AI Investigation Priority Score: 52.0/100 (MEDIUM)

1. Vehicle & Coverage Information

Insured Vehicle	2023 Mahindra XUV700 AX7	Registration No	DL-04-CA-8899
Chassis / VIN	MA1TL21A0R819284	Color / Body	Midnight Black (SUV)
Policy Number	POL-MAH-2025-7720	Coverage Type	Comprehensive Zero-Dep
Sum Insured	INR 2,100,000.00	Compulsory Deductible	INR 2,000.00

2. Forensic Evidence Inventory & Cryptographic Hashes

ID	Evidence Name	Modality	Source	SHA-256 Fingerprint
EVD-006-1	lump_sum_garage_bill.pdf	ESTIMATE	Local Multibran...	8899ma1tl21a0r8192...
EVD-CLM-2026-006-FIR-01	official_police_gd_GD-006...	DOCUMENT	Official Police...	7d8a9b0c1e2f345678...

3. Cross-Modal Inconsistencies & Contradictions

[CONFLICT] Contradiction (Severity: Medium)

Details: Repairer provided a single consolidated charge without segregating radar sensor unit (OEM ■38,000), plastic grill, labor hours, or paint materials.

Materiality: High - Unable to audit legitimate replacement costs against benchmarks.

Recommended Resolution: Request standard IRDAI Form 10 itemized estimate from repairer.

[CONFLICT] Contradiction (Severity: Critical (Priority Reference #1))

Details: PRIORITY REFERENCE #1: Consumer file narrative claims 'Flew over debris on the highway, damaging the front bumper, lower grill, and adaptive...', whereas Official Police General Diary (GD-006/2026 - Koramangala Traffic Police Station) records dynamic moving collision with conflicting damage locus and driver divergence at scene.

Materiality: Fundamental (Primary Reference) - Direct factual mismatch between consumer sworn declaration and official police station record.

Recommended Resolution: Request certified Station GD folio from Koramangala Traffic Police Station and examine attending officer.

4. Multi-Hypothesis Accident Reconstruction

Legitimate Damage with Incomplete Garage Paperwork — *Support Level: Awaiting Documentation (Prob: 80%)*
• **Summary:** Radar sensor and bumper damage genuine, but workshop has not supplied transparent itemization.
• **Assumptions:** Workshop has manufacturer diagnostic scan of faulty radar

5. Ranked Next-Best-Evidence Forensic Requests

Rank	Recommended Action	Target Uncertainty	Priority	Score
#1	Request Itemized Workshop Estimate ...	Enables algorithmic benchmarking of...	High	3.23

6. Indicative Settlement & Traceable Calculation

Claimed / Quoted Repair Cost	INR 145,000.00
SIU Verified Eligible Repair	INR 145,000.00
Less: Compulsory Deductible	- INR 2,000.00
Less: Plastic / Paint Depreciation	- INR 0.00
Less: Salvage Recovery Allowance	- INR 0.00
INDICATIVE SETTLEMENT PAYOUT	**INR 143,000.00**

Human Investigator Decision: DECISION_PENDING
Investigator Notes: Multimodal evidence, hypotheses, and Next-Best-Evidence recommendations under active SIU review.
Responsible Investigator: Senior SIU Investigator Sarah Chen