

CYBEX Solution X-fix Replacement of Warning Label and Owner's Manual

Dear CYBEX Solution X-fix Owner:

This notice has been sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

CYBEX has notified Regal Lager, Inc. that a defect, which relates to motor vehicle safety, exists in certain CYBEX Solution X-fix booster seats manufactured in February 2010. The seats are labeled with a warning statement related to securing an unoccupied booster seat that is inconsistent with CYBEX recommended practices. If a caregiver follows the warning as written, there is an increased risk that the unoccupied booster seat could strike a vehicle occupant and cause injury in a severe crash.

The performance of the Solution X-fix booster seat is not affected when used with a child securely restrained in the seat. Cybex recommends that to fully insure that your booster seat is properly restrained in a crash, when unoccupied, that it be belted in with the vehicle seat belt, even if you are using the LATCH connectors.

The Solution X-fix booster seats affected by this notice were manufactured in February 2010 and have an incorrect warning statement on the warning label affixed to the booster seat, as well as in the Owner's Manual. The enclosed correct warning label and updated Owner's Manual provides warnings to prevent improper use of the booster seat when unoccupied.

According to our records, your Solution X-fix is affected by this action. Please follow the enclosed instructions on how to apply the correct label over the existing label and replace the Owner's Manual that came with your Solution X-fix with the newly updated one. For any questions and additional information, please visit our website www.regallager.com/recall or call us at 800-593-5522 between 8:30 am and 5:30 pm EST.

If you believe that we have failed, or are unable to remedy the defect without charge or within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to http://www.safecar.gov.

We truly apologize for this inconvenience, but trust that you will agree that the safety of your child and other occupants in your vehicle is of the utmost importance. Thank you for using the CYBEX Solution X-fix booster seat and we hope you and your child will enjoy happy and safe travels.

Sincerely yours,

Bet Je

Bengt Lager President

. . . .

Regal Lager, Inc.



Replacement Warning Label and Owner's Manual Instructions

STEP 1: Apply Label

- Identify the existing warning label on the right Head Protector (from the front) beginning with "WARNING! DEATH or SERIOUS INJURY."
- 2. Place the seat at a comfortable working height, or on its side. Make sure the surface of the existing label is dry and free from dirt and grease.
- 3. Carefully peel the white backing off the new label.



4. While holding the upper corners of the clear protective covering, align the new label over the existing label and lower it onto the existing label. Press into position. If your alignment is off, the label can be pulled back with a quick motion and realigned.



5. Rub the label to remove any bubbles and to adhere it. Don't be afraid to put pressure on the clear protective covering.



 Carefully peel off the clear protective covering. If the new label begins to peel up, apply more pressure and try again.
Finish by peeling away the clear plastic covering.



7. The booster seat is ready for use immediately after applying the new label.

STEP 2: Replace Owner's Manual

- 1. Discard the original Owner's Manual found in the pocket on the back of the booster seat.
- 2. Insert the new Owner's Manual into the pocket.