



High Plains Property Maintenance

14847 Madison St

7208109673

randy@highplainsprop.com

Irrigation Billing Detail

Monthly service documentation for Woodglenn Squares HOA

Billing Period: June 1, 2026 – June 30, 2026

INVOICE #57482

Prepared for: **Woodglenn Squares HOA**

INVOICE TOTAL

\$4,610.12

LABOR

\$3,187.50

PARTS

\$1,422.62

JOBS

11

10

BILLING SHEETS

1

WORK ORDERS

0

WET CHECK BILLINGS

WHAT'S INCLUDED

1. **Reconciliation Summary** — line-item breakdown of all charges for this billing period
2. **Billing Sheet Detail** — technician notes, parts, and labor for each service ticket
3. **Work Photos** — site and field photos attached to completed tickets

HOW TO REVIEW

Start with the **Reconciliation Summary** on the next page for a quick overview of all charges. Then turn to the **Billing Sheet Detail** pages for full technician notes and parts used on each visit. Site photos follow each ticket where available. Contact us with any questions before your payment due date.

Invoice Reconciliation Summary

Invoice #57482 · June 1, 2026 – June 30, 2026

REFERENCE #	TYPE	TOTAL
WORK ORDERS		
WO-1777063547494-51	Work Order	\$530.54
Work Orders Subtotal		\$530.54
BILLING SHEETS		
BS-2026-0208	Billing Sheet	\$66.50
BS-2026-0230	Billing Sheet	\$573.80
BS-2026-0221	Billing Sheet	\$121.30
BS-2026-0219	Billing Sheet	\$160.00
BS-2026-0218	Billing Sheet	\$234.10
BS-2026-0217	Billing Sheet	\$190.45
BS-2026-0213	Billing Sheet	\$1,584.05
BS-2026-0207	Billing Sheet	\$173.42
BS-2026-0198	Billing Sheet	\$509.00
BS-2026-0189	Billing Sheet	\$466.96
Billing Sheets Subtotal		\$4,079.58
GRAND TOTAL		\$4,610.12

Total Labor	\$3,187.50
Total Parts	\$1,422.62

Invoice Total

\$4,610.12



Work Order #WO-1777063547494-51 | Invoice #57482

Date: April 27, 2026 | Technician: Admiel | Hours: 2 hrs
C/O Advance HOA Management Denver CO 80237

WORK PERFORMED

- The seeping valve was carefully replaced to ensure optimal performance of the irrigation system. This service was conducted to prevent water loss and maintain the system's efficiency.

FINANCIAL BREAKDOWN

Labor (2 hrs × \$85.00/hr)	\$170.00
Parts Subtotal	\$360.54
TOTAL	\$530.54

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
1" - Pinch Clamp	2	\$0.99	\$1.98
Teflon Tape Application (1)	1	\$1.72	\$1.72
1" Rain Bird Scrubber Valve (PESB Series)	1	\$350.00	\$350.00
Wire Nuts Waterproof	2	\$3.42	\$6.84

WORK PHOTOS





Billing Sheet #BS-2026-0208 | Invoice #57482

Date: June 8, 2026 | Technician: Bryan Krisher | Hours: 0.5 hrs

□ C/O Advance HOA Management Denver CO 80237

WORK PERFORMED

- Replaced the 9V batteries on the DC node system, ensuring it is now fully operational. The system has been tested to confirm functionality and reliability.

FINANCIAL BREAKDOWN

Irrigation Labor (0.5 hrs × \$85.00/hr)	\$42.50
Parts Subtotal	\$24.00
TOTAL	\$66.50

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Duracell 9 Volt Battery	2.00	\$12.00	\$24.00

WORK PHOTOS





Billing Sheet #BS-2026-0230 | Invoice #57482

Date: June 15, 2026 | Technician: Admiel | Hours: 5 hrs
C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- The damaged main irrigation line has been expertly repaired and replaced. This repair ensures that there are no further leaks, restoring the system to optimal functionality.

FINANCIAL BREAKDOWN

Irrigation Labor (5 hrs × \$85.00/hr)	\$425.00
Parts Subtotal	\$148.80
TOTAL	\$573.80

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Fitting – PVC – 2" – 90° Elbow (Slip x Slip)	2.00	\$22.50	\$45.00
Fitting – PVC – 2" – Slip-Fix (Telescoping Repair Coupling)	1.00	\$78.00	\$78.00
2" Coupling	1.00	\$4.95	\$4.95
2" Non-Potable PVC Pipe (Purple, Sch 40) – Per Foot	1.00	\$6.45	\$6.45
Glue & Primer Application (1)	8.00	\$1.80	\$14.40

WORK PHOTOS





Billing Sheet #BS-2026-0221 | Invoice #57482

Date: June 12, 2026 | Technician: Bryan Krisher | Hours: 1 hrs

□ C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- Replaced a broken sprinkler head and nozzle to enhance water distribution and ensure optimal coverage of the irrigation system.

FINANCIAL BREAKDOWN

Irrigation Labor (1 hrs × \$85.00/hr) **\$85.00**

Parts Subtotal **\$36.30**

TOTAL \$121.30

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Head - K-Rain 1804 Pop-Up Spray Body	1.00	\$23.75	\$23.75
Rain Bird Swing Elbow (1/2" Barb x Thread - SBE-050 / SWGE050 / SWGF050)	2.00	\$2.50	\$5.00
Set Nozzle 8', 10', 12' 15'	1.00	\$3.50	\$3.50
Swing Pipe (a.k.a. Funny Pipe / Flex Pipe) 1'	1.00	\$4.05	\$4.05

WORK PHOTOS





Billing Sheet #BS-2026-0219 | Invoice #57482

Date: June 12, 2026 | Technician: Bryan Krisher | Hours: 1 hrs
C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- A comprehensive wire test was conducted, revealing that zones 2, 3, 5, and 7 are all experiencing an open circuit issue.
- This diagnostic process ensures accurate identification of the problem areas within the irrigation system.

FINANCIAL BREAKDOWN

Irrigation Labor (1 hrs × \$85.00/hr)	\$85.00
Parts Subtotal	\$75.00
TOTAL	\$160.00

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Rental - Wire Locator Wire Locator	1.00	\$75.00	\$75.00

WORK PHOTOS





Billing Sheet #BS-2026-0218 | Invoice #57482

Date: June 12, 2026 | Technician: Bryan Krisher | Hours: 2 hrs
C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- Repaired two malfunctioning sprinkler heads to ensure optimal coverage and enhance water distribution efficiency.
- Adjustments were made to improve overall water pressure throughout the irrigation system.

FINANCIAL BREAKDOWN

Irrigation Labor (2 hrs x \$85.00/hr)	\$170.00
Parts Subtotal	\$64.10
TOTAL	\$234.10

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Head - K-Rain 1804 Pop-Up Spray Body	2.00	\$23.75	\$47.50
Set Nozzle 8', 10', 12' 15'	1.00	\$3.50	\$3.50
Rain Bird Swing Elbow (1/2" Barb x Thread - SBE-050 / SWGE050 / SWGF050)	2.00	\$2.50	\$5.00
Swing Pipe (a.k.a. Funny Pipe / Flex Pipe)	2.00	\$4.05	\$8.10

WORK PHOTOS





Billing Sheet #BS-2026-0217 | Invoice #57482

Date: June 12, 2026 | Technician: Bryan Krisher | Hours: 2 hrs
C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- The sprinkler head was relocated 12 feet to enhance the coverage area. This adjustment ensures optimal water distribution across the designated landscape.

FINANCIAL BREAKDOWN

Irrigation Labor (2 hrs × \$85.00/hr)	\$170.00
Parts Subtotal	\$20.45
TOTAL	\$190.45

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Fitting - Insert - 1" - Coupler - 1x3/8 Swing Pipe Fitting - Insert - 1" x 3/8" Swing Pipe Coupler (Reducer Insert)	1.00	\$11.00	\$11.00
Fitting - Swing Pipe - Tee (1/2" Barb Tee) 12'	1.00	\$2.90	\$2.90
Swing Pipe (a.k.a. Funny Pipe / Flex Pipe)	1.00	\$4.05	\$4.05
Rain Bird Swing Elbow (1/2" Barb x Thread - SBE-050 / SWGE050 / SWGF050)	1.00	\$2.50	\$2.50

WORK PHOTOS





Billing Sheet #BS-2026-0213 | Invoice #57482

Date: June 9, 2026 | Technician: Admiel | Hours: 14 hrs

□ C/O Advance HOA Management, PO Box 370390 Denver CO 80237

WORK PERFORMED

- Addressed a significant leak caused by a broken main line at the tee and a leaking male adapter connected to the copper pipe.
- Additionally, replaced a stuck valve to ensure optimal system functionality.

FINANCIAL BREAKDOWN

Irrigation Labor (14 hrs × \$85.00/hr)	\$1,190.00
Parts Subtotal	\$394.05
TOTAL	\$1,584.05

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Fitting - PVC - 2" - Tee (Slip x Slip x Slip)	2.00	\$27.00	\$54.00
Fitting - PVC - 2" - Male Adapter (Slip x Male Thread)	1.00	\$29.90	\$29.90
Fitting - PVC - 2" - 90° Elbow (Slip x Slip)	1.00	\$22.50	\$22.50
Fitting - PVC - 1" - Coupler (Slip x Slip)	2.00	\$9.50	\$19.00
2" Non-Potable PVC Pipe (Purple, Sch 40) - Per Foot	1.00	\$6.45	\$6.45
Fitting - Insert - 3/4" - 90° Coupler (Poly Insert Elbow)	1.00	\$7.00	\$7.00
Fitting - Insert - 1" - Coupler (Poly Insert Coupling)	3.00	\$8.00	\$24.00
Fitting - Insert - 3/4" - Tee (Poly Insert Tee)	3.00	\$9.50	\$28.50
1" - Pinch Clamp	10.00	\$0.99	\$9.90
Glue & Primer Application (1)	16.00	\$1.80	\$28.80
Rain Bird 100-DV 1" Inline Valve	1.00	\$164.00	\$164.00

WORK PHOTOS





Billing Sheet #BS-2026-0207 | Invoice #57482

Date: June 8, 2026 | Technician: Bryan Krisher | Hours: 2 hrs

C/O Advance HOA Management Denver CO 80237

WORK PERFORMED

- Addressed customer complaints regarding dry areas in the irrigation system.
- Located the valve box and identified loose wire connections, which were promptly secured.
- Additionally, discovered another valve that was turned off and reactivated it to ensure proper water flow.

FINANCIAL BREAKDOWN

Irrigation Labor (2 hrs × \$85.00/hr)	\$170.00
Parts Subtotal	\$3.42
TOTAL	\$173.42

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Wire Nuts Waterproof	1.00	\$3.42	\$3.42

WORK PHOTOS





Billing Sheet #BS-2026-0198 | Invoice #57482

Date: June 3, 2026 | Technician: Admiel | Hours: 4 hrs

□ C/O Advance HOA Management Denver CO 80237

WORK PERFORMED

- Replaced the backflow prevention kit to ensure the irrigation system operates safely and efficiently.
- Additionally, replaced a dead battery on a control node to restore full functionality to the system.

FINANCIAL BREAKDOWN

Irrigation Labor (4 hrs × \$85.00/hr)	\$340.00
Parts Subtotal	\$169.00
TOTAL	\$509.00

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Service - BACKFLOW - 2" Backflow Certification	1.00	\$145.00	\$145.00
Duracell 9 Volt Battery	2.00	\$12.00	\$24.00

WORK PHOTOS





Billing Sheet #BS-2026-0189 | Invoice #57482

Date: June 2, 2026 | Technician: Admiel | Hours: 4 hrs

□ C/O Advance HOA Management Denver CO 80237

WORK PERFORMED

- A broken leak in the poly line was identified and addressed, which was causing water to spray towards the owner's house.
- The necessary repairs were made to ensure the irrigation system functions properly and prevents any further water damage to the property.

FINANCIAL BREAKDOWN

Irrigation Labor (4 hrs × \$85.00/hr) **\$340.00**

Parts Subtotal **\$126.96**

TOTAL \$466.96

PARTS & LABOR DETAILS

PART DESCRIPTION	QTY	UNIT PRICE	TOTAL
Fitting - Insert - 1" - Coupler (Poly Insert Coupling)	1.00	\$8.00	\$8.00
1" - Pinch Clamp	4.00	\$0.99	\$3.96
Labor Came to check why this person yard didn't turn on	1.00	\$115.00	\$115.00

WORK PHOTOS

