

PROPELLER MAINTENANCE RECORDS

AT THE PARTY OF TH		
	Log No	
Aircraft Registration No. N595TC		
Propeller Manufacturer McCauley		
Hub ModelB3D32C419-C	_	
Serial No951157		
Blade Design No. 82NHA-5		
Hub Serial No. 951157		
Blade Serial No's. 1. OL 079		
2. OL 084		
3OL 089		
Pitch Range:		
High 33.9+/5 . 14.8 +/2		
Feather Reverse		
Governor Manufacturer McCauley		
Model No. <u>D-20309-40</u>		
Serial No950117		
Date installed on aircraft8/8/95		
Time Between Overhauls 1500 hrs/ 5 yrs		
731		
Aircraft is single engine		

(All applicable information must be filled in)



DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE OF PERSON PERFORMING WORK
	SERVICE	TIME	
			TOTAL brought forward from previous page
	Con		der Aircraft Company FAA Certified Repair Station CMKR305K 7200 N.W. 63rd St., Bethany, OK 73008 ephone (405) 495-8080 FAX (405) 495-8383
	MODEL B3D3	2C419/82NHA	- BEOW - WEST-
	DATE 7-10-	96 TTAF 1	86.1 SMOH W/O M1351
	engine is retu	crankshaft rned to ser	lly balanced by Thunderbird propellers see 6-24-96. Note propeller must be indexed to if removed for any cause. This propeller vice for work preformed under Commander ork order number M1351.
	0'		
	Signed:		er Aircraft Company Repair Station CMKR305K
	Com	mand	ler Aircraft Company A Certified Repair Station CMKR305K
Prope	eller	Teleph	200 N.W. 63rd St., Bethany, OK 73008 none (405) 495-8080 FAX (405) 495-8383
- N	MODEL B3D3	2C419/82NHA	-5 REG# N595mc
_ F	erformed 1	96 TTAF 2	62.7 SMOH W/O M1370
– a	n 100 Hour	Inspection	pection in accordance with Commander 114TC eller has been inspected in accordance with
W	ork perfor	med under Co	ommandation return to service for
a	nd a copy	has been giv	work order is on file at this repair station wen to the aircraft owner.
S	IGNED:		
	FOR (OMMANDER AI	RCRAFT COMPANY REPAIR STATION CMKR305K.
-			OURDED SIGNE OF HEILURGE STATION CMKR305K.
		UB - TOTAL	Dispres Signes of Manufacture Station CMRR305K.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		70	- PL-211-16-12-12-12-12-12-12-12-12-12-12-12-12-12-	TOTALS brought forward from previous page
	BEEN INSPEC	GUN AVIAT THIS PROF TED IN ACCOR INSPECTION AN TO THE WOR	DANCE WITH A D IS AIRWORTHY	114Te duide hours. Renoved niver
-	1	368.1 R.O		NUMS IN Thop WE And Bruted Face,
	Ruit	Buil		Cond. Raw ops checked ob. All Applicable AD'S Tenu 97-17 che
	5569	00292	FS)	& &
	, c			REG: N595TC B3D32C419-C SN: 951157. HOBBS: 412.3 T.T: 412.3 DATE: 10/2/98. 1. C/W ANNUAL INSPECTION I.A.W. COMMANDER MAINT. MANUAL I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED I.A.W. AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY
				MAX BUCHER A&P 569595247 IA.
				MAXAIR AVIATION 16231 WATERMAN DR. VAN NUYS, CA. 91406 (818) 901-7098 (818) 901-7099 FAX.
	6			REG: N595TC
				MAXAIR AVIATION 16231 WATERMAN DR. VAN NUYS, 91406 (818) 901-7098 (1810901-7099 FAX
1-25-00	577.3	5/7.3	5/23	I CERTIFY THAT THIS POPUL HAS BEEN INSPECTED IN ACCORDANCE WITH A PARTIE INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTH CONDITION.
				NAME 1-25-00 TACH TIME 577. 3
				тѕмон_577.3
				SUB-TOTALS this page
			equi big	TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			1 1 mg 11	TOTALS brought forward from previous page
u-al-a	r Sexual 25	6	0.91	REG#: N595TC MAKE: COMMANDER 114TC SER#: 20005 Date: 02-11-2002 TACH:: 552
-Ay-151	Jun 20	5	-	This propeller has been inspected in accordance with annual inspection checklist and was determined to be in airworthy
-33	منالخ	9 44	31/0	condition. Dressed and painted blades.
7,5	h da	1000	/5	Diessed and painted blades.
Lils	ruere.			
		4	LA	
				101
				In Cohust
				JIM OCHWATT IA545118388
			_	
	/ Jensey	244 39	and the same	1.250 202 202 2123 1 100 then 1
	MINE	OT STANK	ETELL SAN	TRA POTTORISE?
STATE	1000	1.3	vaprovu - s.a	PARTITION OF A STATE O
	F'F	THAT	DAT. O	- 2000 and
				SNC nowy
				SUB-TOTALS this page

BELL AVIATION SERVICE

43640 San Francisco Ave. Lancaster, California. 93535 661 886 2277 661 946 6651 Home 240 757 8645 Fax

Propeller Log: N595TC Tach and total time: 573.4 Date: 4-10-2003

Annual inspection:

Minor blending of stone nicks leading edges of propeller blades.

I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Bruce Allan Bell 519805262 A&P IA.

Bruce alle Bell S19805262 AXP I.A.

Airframe & Powerplants mechanic.
Inspection Authorization
519805262
Aircrfixr@aol.com

BELL AVIATION SERVICE

21309 Lakeshore Drive Number 20 California City, California. 93505 661 886 2277

Propeller Log N595TC

Date: October 30, 2004 AFTT and Hobbs: 587.4

- Annual inspection competed in accordance with Commander Aircraft Company Commander Aircraft Company 114B / 114TC Maintenance Manual Inspection check list Revision A.
- AD's checked and in compliance through 2004-20
- I certify that this *Propeller* has been inspected in accordance with an *ANNUAL* inspection and was determined to be in airworthy condition.
 Bruce Allan Bell 519805262 A&P IA.

Bruce allem Bell

California City Airport.

22520 Airport Way.

Hangar Five.

Airframe & Powerplants mechanic.

Inspection Authorization.

Aircrfixr@aol.com

Bell Aviation Service.

21309 Lakeshore drive #20 California City, California. 93505

Propeller Log N595TC Date 01-21-2006 Hobbs, Propeller and AFTT: 600.6 hours.

1-21-2006 AFTT: 600.6 Propeller Total time: 600.6

- Annual inspection completed in accordance with Commander Aircraft Company 114TC check list. Revision A.
- · Dress and lightly blend leading edges of propeller blades.
- · Repaint back side of propeller blades.
- · AD's checked and in compliance through 2006-01.
- I certify that this <u>propeller</u> has been inspected in accordance with <u>annual</u> inspection and was determined to be in airworthy condition.

Bruce Allan Bell 519805262 A&P I.A. Bruce Geen Beet

Hangar Five California City Airport. 22520 Airport way California City, California. 93505

> E-mail: <u>Aircrfixr@aol.com</u> 760 373 9157 Cellular Phone 661 886 2277

APRIL 1,2007

BELL AVIATION SERVICE

17197 Roper Street Hangar 977 Mojave California 93501 Phone (661) 824 – 0555 Cellular Phone 661 728 8584 E-Mail aircrfixr@aol.com

PROPELLER LOG

Commander Aircraft 114TC

AFTT: 601.8 Hobbs: 601.8 ETT: 601.8 PTT: 601.8

- · Annual inspection completed in accordance Appendix D to Part 43.
- Propeller blades lightly dressed and aft portion painted flat black.
- · Propeller hub greased with Aeroshell grease number 6.
- AD 2006-24-07 N.A. Not serviced by Oxford Aviation limited.
- All AD's have been checked and in compliance through 2007-02. I certify this propeller has been inspected in accordance with an annual Inspection and was found to be in an Airworthy condition.

 Bruce Allan Bell 519805262 A&P I.A.

Bruce Celler Bell

MAY 1,2008

BELL AVIATION SERVICE

17197 Roper Street Hangar 977 Mojave California 93501 Phone (661) 824 – 0555 Cellular Phone 661 728 8584 E-Mail aircrfixr@aol.com

PROPELLER LOG

Commander Aircraft 114TC

AFTT: 602.9 Hobbs: 602.9 ETT: 601.8 PTT: 602.9

- Annual inspection completed in accordance Appendix D to Part 43.
- · Propeller blades lightly dressed and aft portion painted flat black.
- · Propeller hub greased with Aeroshell grease number 6.
- All AD's have been checked and in compliance through 2008-04F. I certify this propeller has been inspected in accordance with an annual Inspection and was found to be in an Airworthy condition.

 Bruce Allan Bell 519805262 A&P I.A.

July 10, 2009

EXODUS AIR SERVICE

4555 West Ave "G" Ste#6 (WJF) Lancaster, California 93536 Phone (661) 942-6489 Fax (661) 942 0012 E-Mail Exodusairservice@hotmail.com

N595TC Propeller. Hobbs & TT: 607.0

Annual inspection completed per scope and detail of Appendix D to Part 43.

- Remove and reinstall this propeller on aircraft for alternator belt replacement. Used new O ring seal P/N MS28775-228.
- Dress propeller blade leading edges and paint aft portion of blades flat black.
- · AD's checked and in compliance through 2009-14F.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Bruce Allan Bell A&P I.A. 519805262

Bruce allen Bell

September 25, 2010

BELL AVIATION SERVICE

P.O. Box 4971 Phone: 661 718 9671

Lancaster, California 93539
Aircrfixr@aol.com
A&P I.A. 3444107

N595TC Propeller Log McCauley B3D32C419-C S/N 951157 Propeller total time and Hobbs: 607.3

Annual inspection completed in accordance with Appendix D to Part 43.

• All Airworthiness Directives are in compliance through 2010-18F

I certify that this **propeller** has been inspected in accordance with an annual Inspection and was found to be in an airworthy condition.

Bruce Allan Bell A&P I.A. 3444107

Bruce allen neel

BELL AVAIATION SERVICE

BRUCE ALLAN BELL

44401 Benald Street, Lancaster, California 93535

Phone: 661 718 9671

Aircrfixr@aol.com

A&P 3444107 I.A.

N595TC

McCauley Propeller Model: B3D32C419 S/N: 951157 Total Time 610.5 Hours.

Annual inspection performed per Scope and Detail of Appendix D to Part 43.

All airworthiness directives are in compliance through 2012-04.

Check lists and details of work performed are on file.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Bruce Allan Bell A&P 3444107 I.A. Bruce Cler Beet 03/04/2012

BELL AVIATION SERVICE

BRUCE ALLAN BELL A&P 3444107I.A.
1150 CHAGAL AVE. LANCASTER, CALIFORNIA. 93535

N595TC Commander 114TC S/N: 20005
Propeller McCauley Model: B3D32C419-C S/N: 951157
August 27, 2013 Hobbs & Propeller Total Time: 611.1
Annual inspection performed Scope and Detail of Appendix D to Part 43.

Airworthiness Directives are in compliance through 2013-17.
 I certify that this Aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Bruce Allan Bell A&P 3444107 I.A.

TELEPHONE: 661 718 9671

Bruce allan Bell

Page 3 of 3 E-Mail: Aircrfixr@aol.com

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME							
		74	1 5	TOTALS brought forward from previous page						
	ACFT Model: Commander 114TC			GIBBS SERVICE CENTER Date: 3-21-2014						
	Serial No.:	20005		Montgomery Field, San Diego, CA 92123 W.O. No.: 15615						
	Reg. No.: N595TC			FAA Approved Repair Station VT3R931L TPT: 612.1						
	Prop. Mfg.: McCauley			Prop. Model: B3D32C419-C/82NHA-5 Prop. S/N: 951157						
	SMOH: 612.1			Hobbs: 612.1 Airframe: 612.1						
	Annual inspection completed per the Commander Aircraft Co.,114TC AMM, 50 hr/ 100 hr Inspection Checklist. Inspected spinner, bulkhead, blades and hub. AD notes checked and are current 3-21-2014. ATP Navigator Content Revision: 3-25-2014.									
	Aviation Regu	nd/or compone ulations and way under Order	as found airw	above repaired/replaced and inspected in accordance with current Federal orthy for return to service. Pertinent details of the repair/replacement are on file						
	Date: 3-21	-2014		Signed: Jeff Runyon						
4-2-16	T-1ccm			I CERTIFY THAT THIS Profes						
1717	-T-688.g			BEEN INSPECTED IN ACCORDANCE WITH A						
,	*			De his Anno Los Los INSPLUTION AND WAS FOUND / ////						
A 1877										
£ .	0 1 "	_		TO BE IN AIRWORTHY CONDITION. July Surv. + 435 7559						
4-20-16	1 CERTIFY THAT THIS _ POD HAS									
	BEEN INSPECTED IN ACCORDANCE WITH A									
	160/h/ Auny INSPECTION AND WAS FOUND and Sold of the									
				TO BE IN AIRWORTH ONDITION.						
***		-		IB3575997						
×	Arispe Aviation LLC 1704 Canyon Wren Dr. McKinney, Tx 75071 Commander 114TC N595TC S/N 20005 Tach Time 805.4 Date 01Jul17 McCauley Model B3D32C419-C/82NHA-5 S/N 951157 TSMO 805.4									
	Performed annual inspection I.A.W. Commander 114 Service Manual and Manufacturers Maintenance Manual All A.D.'s complied with at this time. No New A.D.'s Inspected Hub, Spinner, Blades and Bulkhead no defects noted at this time.									
	I certify this propeller has been inspected I.A.W. a 100Hr/Annual inspection using the aircraft maintenance manual and FAR part 43 appendix D and was found to be in an airworthy condition at this time									
	Anthony Arispe I.A. 3381156									
	Signature			Date						
	\$	1 2	1 1							
			*	SUB-TOTALS this page						
	7			- COD-101ALS tills page						
40			Ř	TOTALS—Carry forward to next page						