

PROPELLER MAINTENANCE RECORDS

82	
	Log No
Aircraft Registration No. N595TC	
Propeller Manufacturer McCauley	
Hub ModelB3D32C419-C	-
Serial No951157	
Blade Design No. 82NHA-5	
Hub Serial No. 951157	
Blade Serial No's. 1. OL 079	
2. OL 084	
3OL 089	
Pitch Range:	
High 33.9+/5 . 14.8 +/2	
Feather Reverse	
Governor Manufacturer McCauley	
Model NoD-20309-40	
Serial No. <u>950117</u>	
Date installed on aircraft8/8/95	
Time Between Overhauls1500 hrs/ 5 yrs	
Aircraft is single engine	

(All applicable information must be filled in)



DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE OF PERSON PERFORMING WORK
			TOTAL brought forward from previous page
_			
	Con		der Aircraft Company FAA Certified Repair Station CMKR305K 7200 N.W. 63rd St., Bethany, OK 73008 ephone (405) 495-8080 FAX (405) 495-8383
	MODEL_B3D3	32C419/82NHA	- F DEC# 11505-1-
	DATE 7-10-	96 TTAF 1	REG# N595CA S/N 951157 B86.1 SMOH W/O M1351
	engine is retu	crankshaft rned to ser t Company w	ally balanced by Thunderbird propellers see 6-24-96. Note propeller must be indexed to if removed for any cause. This propeller vice for work preformed under Commander ork order number M1351.
			er Aircraft Company Repair Station CMKR305K
	Com	mand	or Aironoft C
Prope	eller	72 Teleph	ler Aircraft Company AA Certified Repair Station CMKR305K 200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383
^	eller MODEL B3D3	72 Teleph 2C419/82NHA	200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383 A=5 REG# N595TC S/N 951157
M	eller MODEL B3D3 DATE 08-28- Performed 1 guidelines. an 100 Hour work perform	Teleph 2C419/82NHA 96 TTAF 2 00 Hour Ins This prop Inspection med under Co	200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383 1-5 REG# N595TC S/N 951157 262.7 SMOH
M	eller MODEL B3D3 DATE 08-28- Performed 1 guidelines. an 100 Hour work perform M1370. A cound a copy 1	Teleph 2C419/82NHA 96 TTAF 2 00 Hour Ins This prop Inspection med under Co ppy of this has been given	200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383 A-5 REG# N595TC S/N 951157 Depection in accordance with Commander 114TC eller has been inspected in accordance with and is approved for return to service for commander Aircraft Company work order number work order is on file at this repair station wen to the aircraft owner.
M	eller MODEL B3D3 DATE 08-28- Performed 1 guidelines. an 100 Hour work perform M1370. A cound a copy 1	Teleph 2C419/82NHA 96 TTAF 2 00 Hour Ins This prop Inspection med under Co ppy of this has been given	200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383 A-5 REG# N595TC S/N 951157 Dection in accordance with Commander 114TC eller has been inspected in accordance with and is approved for return to service for commander Aircraft Company work order number
M	eller MODEL B3D3 DATE 08-28- Performed 1 guidelines. an 100 Hour work perform M1370. A cound a copy 1 FOR C	Teleph 2C419/82NHA 96 TTAF 2 00 Hour Ins This prop Inspection med under Co ppy of this has been given	200 N.W. 63rd St., Bethany, OK 73008 hone (405) 495-8080 FAX (405) 495-8383 A-5 REG# N595TC S/N 951157 Dection in accordance with Commander 114TC eller has been inspected in accordance with and is approved for return to service for ommander Aircraft Company work order number work order is on file at this repair station wen to the aircraft owner.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
	WITH RESPECT		DANCE WITH A D IS AIRWORTHY K PERFORMED TIME 363-	MUTE duidebines. Renoved niver
	TACH TIME_	368-1 R.O	736743	
	Rul	Buil		Cond. Raw ops checked ob. All Applicable AD'S Thom 97-17 ches
	5569	00292	FA	Es -
				REG: N595TC B3D32C419-C SN: 951157. HOBBS: 412.3 T.T: 412.3 DATE: 10/2/98. 1. C/W ANNUAL INSPECTION I.A.W. COMMANDER MAINT. MANUAL I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED I.A.W. AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
				MAX BUCHER A&P 569595227 IA.
				MAXAIR AVIATION 16231 WATERMAN DR. VAN NUYS, CA. 91406 (818) 901-7098 (818) 901-7099 FAX.
				REG: N595TCB3D32C419-CSN: 951157 HOBBS: 483.1T.T.: 483.1DATE: 11/04/99 1. C/W ANNUAL INSPECTION I.A.W. COMMANDER MAINT. MANUAL 2. DRESSED & REPAINTED PROPELLER I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED I.A.W. AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWOTHY CONDITION. THE PROPERTY FURTHER A&P573866271 IA MAXAIR AVIATION
				16231 WATERMAN DR. VAN NUYS, 91406 (818) 901-7098 (1810901-7099 FAX
1-25-60	517.3	5/7.3	5/7.3	I CERTIFY THAT THIS POPUL HAS BEEN INSPECTED IN ACCORDANCE WITH A PARTIE INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTH CONDITION.
				NAME 4 / John NO ASP5451187884
				DATE 11-25-00 TACH TIME 577. 3 TSMOH 577. 3
				SUB-TOTALS this page TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
			0	TOTALS brought forward from previous page	
e algo	E.	0	5 800	REG#: N595TC MAKE: COMMANDER 114TC SER#: 20005 Date: 02-11-2002 TACH:: 552	1
200	- Ca 30	5	3.00	This propeller has been inspected in accordance with annual inspection checklist and was determined to be in airworthy	
0]	Llin	1	July 5	condition. Dressed and painted blades.	
/ 3	4 %	المالية	المح المال	Drossed and painted blades.	
حلسا	1.16		- STA		
		*	1.43		
				10/	
				JIM OCHWATT IA545118388	
			-		
					-
_					
			-		
	/ NBSU	MAH 30	1200	FIANT VALUE SEE SEE SEE SEE SEE	
	20.38	OT THE DA		ESCHONANDA	
STONE S	200	in Ra	N. Allahan	THE THICK HEAD	
	per la constant	£ 3MT	DAT. Y	TO SEED HEAD	
				STE HOUSE	
		,			
				SUB-TOTALS this page	

TOTALS—Carry forward to next page

BELL AVIATION SERVICE

43640 San Francisco Ave. Lancaster, California. 93535 661 886 2277 661 946 6651 Home 240 757 8645 Fax

Propeller Log: N595TC Tach and total time: 573.4 Date: 4-10-2003

Annual inspection:

Minor blending of stone nicks leading edges of propeller blades.

I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Bruce Allan Bell 519805262 A&P IA.

Bruce Olly Bell S19805262 AXP I.A.

Airframe & Powerplants mechanic.
Inspection Authorization
519805262
Aircrfixr@aol.com

BELL AVIATION SERVICE

21309 Lakeshore Drive Number 20 California City, California. 93505 661 886 2277

Propeller Log N595TC

Date: October 30, 2004 AFTT and Hobbs: 587.4

- Annual inspection competed in accordance with Commander Aircraft Company Commander Aircraft Company 114B / 114TC Maintenance Manual Inspection check list Revision A.
- AD's checked and in compliance through 2004-20
- I certify that this *Propeller* has been inspected in accordance with an *ANNUAL* inspection and was determined to be in airworthy condition.
 Bruce Allan Bell 519805262 A&P IA.

Bruce allem Bell

California City Airport.

22520 Airport Way.

Hangar Five.

Airframe & Powerplants mechanic.

Inspection Authorization.

Aircrfixr@aol.com

Bell Aviation Service.

21309 Lakeshore drive #20 California City, California. 93505

Propeller Log N595TC Date 01-21-2006 Hobbs, Propeller and AFTT: 600.6 hours.

1-21-2006 AFTT: 600.6 Propeller Total time: 600.6

- Annual inspection completed in accordance with Commander Aircraft Company 114TC check list. Revision A.
- · Dress and lightly blend leading edges of propeller blades.
- · Repaint back side of propeller blades.
- AD's checked and in compliance through 2006-01.
- I certify that this <u>propeller</u> has been inspected in accordance with <u>annual</u> inspection and was determined to be in airworthy condition.

Bruce Allan Bell 519805262 A&P I.A. Bruce allan Bell

Hangar Five California City Airport. 22520 Airport way California City, California. 93505

> E-mail: <u>Aircrfixr@aol.com</u> 760 373 9157 Cellular Phone 661 886 2277

APRIL 1,2007

BELL AVIATION SERVICE

17197 Roper Street Hangar 977 Mojave California 93501 Phone (661) 824 – 0555 Cellular Phone 661 728 8584 E-Mail aircrfixr@aol.com

PROPELLER LOG

Commander Aircraft 114TC

AFTT: 601.8 Hobbs: 601.8 ETT: 601.8 PTT: 601.8

- Annual inspection completed in accordance Appendix D to Part 43.
- Propeller blades lightly dressed and aft portion painted flat black.
- Propeller hub greased with Aeroshell grease number 6.
- AD 2006-24-07 N.A. Not serviced by Oxford Aviation limited.
- All AD's have been checked and in compliance through 2007-02. I certify this **propeller** has been inspected in accordance with an **annual**

Inspection and was found to be in an Airworthy condition. Bruce Allan Bell 519805262 A&P I.A.

Bruce Celler Bell

MAY 1,2008

BELL AVIATION SERVICE

17197 Roper Street Hangar 977 Mojave California 93501 Phone (661) 824 – 0555 Cellular Phone 661 728 8584 E-Mail aircrfixr@aol.com

PROPELLER LOG

Commander Aircraft 114TC

AFTT: 602.9 Hobbs: 602.9 ETT: 601.8 PTT: 602.9

• Annual inspection completed in accordance Appendix D to Part 43.

- · Propeller blades lightly dressed and aft portion painted flat black.
- Propeller hub greased with Aeroshell grease number 6.
- All AD's have been checked and in compliance through 2008-04F. I certify this **propeller** has been inspected in accordance with an **annual** Inspection and was found to be in an Airworthy condition.

 Bruce Allan Bell 519805262 A&P I.A.

July 10, 2009

EXODUS AIR SERVICE

4555 West Ave "G" Ste#6 (WJF) Lancaster, California 93536 Phone (661) 942-6489 Fax (661) 942 0012 E-Mail Exodusairservice@hotmail.com

N595TC Propeller. Hobbs & TT: 607.0

Annual inspection completed per scope and detail of Appendix D to Part 43.

- Remove and reinstall this propeller on aircraft for alternator belt replacement. Used new O ring seal P/N MS28775-228.
- Dress propeller blade leading edges and paint aft portion of blades flat black.
- AD's checked and in compliance through 2009-14F.

I certify that this **propeller** has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Bruce Allan Bell A&P I.A. 519805262

Bruce allen Beer

September 25, 2010

BELL AVIATION SERVICE

P.O. Box 4971 Phone: 661 718 9671 Lancaster, California 93539
<u>Aircrfixr@aol.com</u>
A&P I.A. 3444107

N595TC Propeller Log McCauley B3D32C419-C S/N 951157 Propeller total time and Hobbs: 607.3

Annual inspection completed in accordance with Appendix D to Part 43.

• All Airworthiness Directives are in compliance through 2010-18F

I certify that this **propeller** has been inspected in accordance with an annual Inspection and was found to be in an airworthy condition.

Bruce Allan Bell A&P I.A. 3444107

Bruce allen neel

BELL AVAIATION SERVICE

BRUCE ALLAN BELL

44401 Benald Street, Lancaster, California 93535

Phone: 661 718 9671

Aircrfixr@aol.com

A&P 3444107 I.A.

N595TC

McCauley Propeller Model: B3D32C419 S/N: 951157 Total Time 610.5 Hours.

Annual inspection performed per Scope and Detail of Appendix D to Part 43.

All airworthiness directives are in compliance through 2012-04.

Check lists and details of work performed are on file.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Bruce Allan Bell A&P 3444107 I.A. Bruce Cler Beet 03/04/2012



BELL AVIATION SERVICE

BRUCE ALLAN BELL A&P 3444107I.A.
1150 CHAGAL AVE. LANCASTER, CALIFORNIA. 93535

N595TC Commander 114TC S/N: 20005
Propeller McCauley Model: B3D32C419-C S/N: 951157
August 27, 2013 Hobbs & Propeller Total Time: 611.1
Annual inspection performed Scope and Detail of Appendix D to Part 43.

• Airworthiness Directives are in compliance through 2013-17.

I certify that this Aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Bruce Allan Bell A&P 3444107 I.A.

TELEPHONE: 661 718 9671

Bruce allan Bell

Page 3 of 3 E-Mail: Aircrfixr@aol.com

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME		WORK PERFORMED— NO. OF PERSON PERFORMING WORK			
				TOTALS brought forward from previous	ous page			
	ACFT Model:	Command 114TC	der	GIBBS SERVICE CENTER	Date: 3-21-2014	-		
	Serial No.:	20005		Montgomery Field, San Diego, CA 92123	W.O. No.: 15615			
	Reg. No.:	N595TC		FAA Approved Repair Station VT3R931L	TPT: 612.1	- 4		
	Prop. Mfg.:	McCauley		Prop. Model: B3D32C419-C/82NHA-5	Prop. S/N: 951157			
	SMOH:	612.1		Hobbs: 612.1 Airframe: 612.1 ommander Aircraft Co.,114TC AMM, 50 hr/ 100 hr Inspection Checklist, Inspected notes checked and are current 3-21-2014. ATP Navigator Content Revision: 3-25-				
	Annual inspect spinner, bulkh 2014.	ction complete lead, blades a	d per the Co					
	The aircraft ar Aviation Regu at this agency	lations and wa	as found airv	above repaired/replaced and inspected in according for return to service. Pertinent details of	cordance with current Federal of the repair/replacement are on file			
	Date: 3-21-	-2014		Signed: Jeff Runyon				
1. 3.16	T (oc.	2		I CERTIFY THAT THIS Pro	P HAS			
4-7-15	-T-688.9			BEEN INSPECTED IN ACCOR	10.50.4			
				tool A INCO. TION A	NO WAS FOUND (/ //			
				DANAMON INSPECTION A	DITION. July 1. 7.435	7~		
Sec. 7 5				TO BE IN AIRWORTHY CONE	OHION. LEUS SURV. 41153	257		
5-20-16	1-786.5			I CERTIFY THAT THIS	P			
	7.7			PEEN INCOCATED IN ACC	HAS			
-				BEEN INSPECTED IN ACCORDANCE WITH A 100/hs Asum INSPECTION AND WAS FOUND Allegha				
	100004	274. 2.1		TO BE IN AIRWORTH ONDITION. THE STATE OF THE				
	,			*	747575	/_		
1								
					*			
-								
			-	,				
			ļ.,					
				-				
					*			
				SUB-TOTALS this page				
	-			TOTALS				