

F3 adaptation: predictable task work and whole-port depletion
K0
K1
K2
K3
K4
Whole-port account [J]
Residual account [J]
TCP x progress [m]
Normal force [N]
Time [s]
Time [s]
Time [s]
Time [s]