



DS Blend Weight (0 = reaching, 1 = polishing)



Signed Surface Distance (+ above, - in contact)



Contact Normal Force

