STATEMENT OF VALUES

Commercial Property Insurance — Mixed Occupancy Portfolio

Field	Detail
Named Insured	Crestview Hospitality & Retail Properties LLC
Policy Period	July 1, 2026 — June 30, 2027
Valuation Basis	Replacement Cost Value (RCV) — Agreed Value (no co-insurance)
Appraisal Platform	Cotality Marshall & Swift RCT Express — March 2026
Total Insured Value (TIV)	$39,540,000
SOV Prepared By	Thomas R. Crestview III, Managing Member
SOV Date	May 10, 2026

Authorized Signature: _____ *Date:* _____

SECTION 1 — MASTER STATEMENT OF VALUES

Loc #	Address	City/State	Occupancy	Construction	ISO	Yr Built	Sq Ft	Bldg RCV	BPP	BI/EE
LOC-1	124 Bourbon St	New Orleans, LA 70116	Hospitality / Hotel	Joisted Masonry	Class 2	1985	68,000	$12,400,000	$1,800,000	$3,200,000
LOC-2	5501 E 41st St	Tulsa, OK 74135	Retail — General	NC Light Steel	Class 3	2005	45,000	$5,200,000	$680,000	$820,000
LOC-3	3800 NE 2nd Ave	Miami, FL 33137	Restaurant / Food Svc	Masonry Non-Comb.	Class 4	2015	8,500	$2,100,000	$420,000	$960,000
LOC-4	1420 5th Ave	Seattle, WA 98101	Mixed Use Office+Retail	Mod. Fire Resistive	Class 5	1999	52,000	$9,800,000	$760,000	$1,400,000
TOTAL							**173,500**	**$29,500,000**	**$3,660,000**	**$6,380,000**

SECTION 2 — LOCATION DETAIL SHEETS

LOC-1 | 124 Bourbon Street, New Orleans, LA 70116

Attribute	Detail
Full Address	124 Bourbon Street, New Orleans, LA 70116 (Orleans Parish)
Occupancy	Hospitality / Hotel — 42-room boutique hotel; ground-floor bar and restaurant
Tenant(s)	Owner-operated by Crestview; no third-party tenants
Construction	Joisted Masonry — Class 2; brick/CMU exterior walls; wood floor joists; balloon-frame interior partitions
Year Built	1985
Gross Area	68,000 sq. ft. (7 stories including rooftop terrace)
Number of Rooms	42 guest rooms; 1 event space (capacity 120); ground-floor bar (capacity 60)
Roof	Built-up asphalt (BUR) 4-ply; installed 2008 (17 yrs); exceeds recommended replacement threshold; ACV basis on roof — replacement plan required (Exhibit H)
Electrical	200A commercial; last updated 2001 (24 yrs); copper wiring; no knob-and-tube confirmed
Plumbing	Mixed system: CPVC in upper floors (1985); confirmed galvanized in basement and lower service areas (40 yrs) — A9: 80 pts; replacement mandatory — Exhibit N
HVAC	Carrier split-system units (per floor); installed 2010 (15 yrs); annual service contract
Sprinkler	Partial — 60% coverage; guest rooms covered (NFPA 13R); basement, kitchen, ground floor bar NOT sprinklered — E1: 60 pts; extension plan 180 days — Exhibit N
Fire Alarm	Local alarm + smoke detectors throughout; NO UL central station monitoring — E3: 20 pts; upgrade to central station recommended as condition

Attribute	Detail
Security	ADT central monitored burglar alarm; no video surveillance
Last Fire Inspection	20 months ago (E6: 70 pts) — new inspection within 30 days of bind required
FEMA Flood Zone	Zone VE/V — coastal high-hazard; direct Gulf of Mexico tidal flood exposure; NFIP policy in force ($500,000)
Wildfire Score	0 — Low (urban New Orleans; no WUI exposure)
Wind Zone	Zone 3 — Gulf Coast (ASCE 7-22; 140 mph design wind speed)
Hail Score	3 — Low
ISO PPC	Class 5
Vacancy	0% — fully operational hotel
Deferred Maintenance	Score 7 — Significant: plumbing (galvanized replacement), roof (overdue replacement), exterior masonry repointing, elevator modernization — Exhibit V
Mortgagee	First Horizon Bank — approx. $7,200,000 outstanding
Building RCV	$12,400,000 (Cotality Marshall & Swift RCT Express, March 2026 — $182.35/sf; elevated for historic French Quarter construction)
BPP	$1,800,000 (FF&E, commercial kitchen equipment, bar equipment, AV/IT systems, linens and operating inventory owned by Crestview)
Business Income / EE	$3,200,000 (18-month; Actual Loss Sustained basis)
TIV	$17,400,000
ITV	100%

LOC-2 | 5501 E 41st Street, Tulsa, OK 74135

Attribute	Detail
Full Address	5501 East 41st Street, Tulsa, OK 74135 (Tulsa County)
Occupancy	Retail — General Merchandise; strip retail center (6 inline units)
Tenant(s)	Five retail tenants (national and regional brands); 1 unit vacant (~7,500 sf)
Construction	Non-Combustible Light Steel — Class 3; steel frame; gypsum board; masonry veneer facade
Year Built	2005
Gross Area	45,000 sq. ft.
Roof	TPO 45-mil; installed 2005 (20 yrs); hail damage documented (2025 loss); replacement budgeted Q3 2026 — Class 4 UL 2218 hail-resistant specification — Exhibit H
Electrical	400A copper; installed 2005 (20 yrs)
Plumbing	CPVC; installed 2005 (20 yrs)
HVAC	Rooftop RTU per unit; replaced 2015 (10 yrs)
Sprinkler	NFPA 13 Wet 100%
Fire Alarm	UL Central Station (ADT)
Security	ADT central + 8-camera IP video

Attribute	Detail
Last Fire Inspection	9 months ago — compliant
FEMA Flood Zone	Zone AH/AO — moderate flood hazard
Hail Score	9 — HIGH (Tornado Alley; 2.0-in average event frequency)
Wind Zone	Zone 1-2 — Inland; tornado exposure per ASCE 7
ISO PPC	Class 4
Vacancy	~17% (one unit, 7,500 sf)
Deferred Maintenance	Score 4 — Moderate: roof replacement (scheduled), parking lot drainage improvement — Exhibit V
Mortgagee	BancFirst Oklahoma — approx. $2,800,000 outstanding
Building RCV	$5,200,000 (Cotality Marshall & Swift RCT Express, March 2026 — $115.56/sf)
BPP	$680,000 (landlord-owned TIAs and common area equipment)
Business Income / EE	$820,000 (18-month; ALS basis)
TIV	$6,700,000

LOC-3 | 3800 NE 2nd Avenue, Miami, FL 33137

Attribute	Detail
Full Address	3800 NE 2nd Avenue, Miami, FL 33137 (Miami-Dade County — Wynwood district)
Occupancy	Restaurant / Food Service — full-service waterfront restaurant; seating 180; private dining room
Tenant(s)	Owner-operated by Crestview (brand: The Coral Terrace)
Construction	Masonry Non-Combustible — Class 4; CMU walls; non-combustible steel roof deck
Year Built	2015
Gross Area	8,500 sq. ft.
Roof	TPO 60-mil; installed 2018 (8 yrs); Miami-Dade NOA rated; current condition — Exhibit D
Fire Suppression	Ansul R-102 pre-engineered hood suppression system (commercial kitchen); inspected semi-annually
Sprinkler	NFPA 13 Wet 100%
Fire Alarm	UL Central Station (SimplexGrinnell)
Security	Central + 10-camera IP video + 24/7 guard service
FEMA Flood Zone	Zone AE — Miami-Dade; NFIP supplement in force
Wind Zone	Zone 3 HVHZ — 185 mph design wind; FBC 7th Edition (2023) compliant
Hail Score	2 — Low
ISO PPC	Class 2
Building Code	FBC 7th Edition (2023) — construction 2015; compliant with current edition; documentation enclosed — Exhibit J
Vacancy	0% — fully operational

Attribute	Detail
Building RCV	$2,100,000 (Cotality Marshall & Swift RCT Express, March 2026 — $247.06/sf; reflects high-finish restaurant build-out and HVHZ construction premium)
BPP	$420,000 (commercial kitchen equipment, bar equipment, furniture, AV systems — owned by Crestview)
Business Income / EE	$960,000 (18-month; ALS basis)
TIV	$3,480,000

LOC-4 | 1420 5th Avenue, Seattle, WA 98101

Attribute	Detail
Full Address	1420 5th Avenue, Seattle, WA 98101 (King County — downtown Seattle)
Occupancy	Mixed Use — Office (floors 2–5) and Retail (ground floor)
Tenant(s)	Three office tenants (floors 2–4, fully leased); Floor 5 vacant (10,000 sf); two ground-floor retail units (fully leased)
Construction	Modified Fire Resistive — Class 5; partial 1-hr fire rating; reinforced concrete lower structure; steel/masonry upper levels; renovated 2008 and 2018
Year Built	1999
Gross Area	52,000 sq. ft. (5 stories + basement)
Roof	EPDM 45-mil; installed 2010 (15 yrs); current condition — upper end of 8-15 yr band
Electrical	600A copper; updated 2008 (17 yrs)
Plumbing	CPVC; original 1999, partially updated 2008 (17 yrs confirmed CPVC)
HVAC	VRF (Variable Refrigerant Flow) system; installed 2018 (7 yrs)
Sprinkler	NFPA 13 Wet 100%
Fire Alarm	UL Central Station (ADT)
Security	ADT central + 12-camera IP video; no guard service
Last Fire Inspection	11 months ago — compliant
Backup Power	Generator — single unit; adequate for life safety and elevator
FEMA Flood Zone	Zone AH/AO — Seattle flood fringe (Puget Sound tidal / storm surge)
Wildfire Score	30 — Moderate (WUI fringe; proximity to eastern King County interface zones)
Wind Zone	Zone 1-2 — Pacific Northwest inland
Earthquake PML	18% — Cascadia Subduction Zone + Seattle Fault (USGS); C6: 100 pts
Hail Score	1 — Low
ISO PPC	Class 3
Vacancy	~19% (floor 5 office space; active marketing)
ADA Compliance	Pending improvements — elevator modernization and accessible restroom upgrades; documented plan and budget enclosed — Exhibit Q
Deferred Maintenance	Score 3 — Moderate: elevator modernization (ADA overlap), roof inspection and seam repair, facade re-caulking — Exhibit V

Attribute	Detail
Mortgagee	Pacific Premier Bank — approx. $5,400,000 outstanding
Building RCV	$9,800,000 (Cotality Marshall & Swift RCT Express, March 2026 — $188.46/sf)
BPP	$760,000 (landlord-owned TIAs and common area finishes)
Business Income / EE	$1,400,000 (18-month; ALS basis)
TIV	$11,960,000

SECTION 3 — VALUE SCHEDULE BY COVERAGE LINE

3.1 Building RCV Summary

Loc	Address	Occupancy	Construction	Sq Ft	Cost/SF	Bldg RCV	Prior RCV	Change
LOC-1	124 Bourbon St, NO	Hotel	JM Class 2	68,000	$182.35	$12,400,000	$11,600,000	+6.9%
LOC-2	5501 E 41st, Tulsa	Retail	NC Class 3	45,000	$115.56	$5,200,000	$4,900,000	+6.1%
LOC-3	3800 NE 2nd, Miami	Restaurant	MNC Class 4	8,500	$247.06	$2,100,000	$1,950,000	+7.7%
LOC-4	1420 5th Ave, Seattle	Mixed Use	MFR Class 5	52,000	$188.46	$9,800,000	$9,300,000	+5.4%
TOTAL				**173,500**		**$29,500,000**	**$27,750,000**	**+6.3%**

LOC-1 RCV increase (6.9%) reflects construction cost escalation for historic French Quarter masonry restoration; specialist contractor premium included in Cotality Marshall & Swift estimate.

3.2 ITV Certification (Parameter F7)

Loc	Occupancy	Building RCV	Limit Requested	ITV %	F7 Action	Agreed Value?
LOC-1	Hotel — Bourbon St	$12,400,000	$12,400,000	100%	None — Full RCV	Yes
LOC-2	Retail — Tulsa	$5,200,000	$5,200,000	100%	None — Full RCV	Yes
LOC-3	Restaurant — Miami	$2,100,000	$2,100,000	100%	None — Full RCV	Yes
LOC-4	Mixed Use — Seattle	$9,800,000	$9,800,000	100%	None — Full RCV	Yes
PORTFOLIO		**$29,500,000**	**$29,500,000**	**100%**	**Agreed Value requested**	**Yes — all locations**

— END OF STATEMENT OF VALUES —

For questions contact: Thomas R. Crestview III | (504) 555-0100 | t.crestview@crestviewproperties.com